

THE PENNSYLVANIA BLUE PROJECT

Documentation and Conditions Survey of the Exterior Marble Masonry

THE SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PENNSYLVANIA

Prepared by:

The Architectural Conservation Laboratory and Research Center
051 Duhring Wing
University of Pennsylvania

Frank Matero, Director, ACL
John Hinchman, Supervising Conservator (2003)
Guy Munsch, Supervising Conservator (1999)
Kerry Johnston, Project Assistant
A. Elena Charola, Conservation Scientist

Prepared for:

The National Park Service
Independence National Historical Park
Philadelphia, Pennsylvania

Table of Contents

Acknowledgements	i
1.0 Introduction	1
2.0 Project Overview.....	4
2.1 Phase 1 (1999).....	4
2.2 Phase 2 (2003).....	5
3.0 Documentation and Archival Research	7
4.0 Construction and Conservation History	9
5.0 Marble Decay: An Overview	19
6.0 Existing Conditions	22
6.1 Condition Recording and Assessment: A Conservator's Guide	22
6.2 Conditions Recorded: Phase 1	24
6.3 Conditions Recorded: Phase 2	24
7.0 Condition Assessment Drawings.....	26
8.0 Material Analysis.....	52
8.1 Analysis Summary	54
8.2 Sample Locations.....	57
9.0 Recommendations for Future Phases	58
10.0 Bibliography	59
10.1 Published Sources.....	59
10.2 Unpublished Sources	68
11.0 Appendix	71
11.1 Appendix A. Guidelines	71
11.2 Appendix B. Budgeting: Hours Allocated by Task.....	75
11.3 Appendix C: Masonry Conditions Glossary.....	77
11.4 Appendix D: Overview of 1999 Database of Conditions	108
Index.....	109

Acknowledgements

The completion of all phases of the exterior masonry conditions assessment of the Second Bank of the United States would not have been possible without the dedicated efforts of many. Graduate and post-graduate interns from the Historic Preservation Program at the University of Pennsylvania committed a tremendous amount of time and energy to complete the conditions survey, archival research and preliminary analyses. Thank you to Lori Aument, Elsa Bourguignon, Catherine Dewey, Claudia Harbert, Diane Jackier, Margaret Newman, John Glavan, Lauren Hegerty, John Howard, Kerry Johnston, and Sophia Middlebrook.

This project has been developed through the Cooperative Agreement between the National Park Service, Independence National Historical Park and the University of Pennsylvania. Members of both organizations have contributed to the coordination, implementation, funding and continued research into preservation issues at the Second Bank of the United States. At the University of Pennsylvania, Frank Matero, Chairman of the Graduate Program in Historic Preservation, A. Elena Charola, Guy Munsch, John Hinchman, and Kerry Johnston have been integral to the participation of the University. At the National Park Service the tireless efforts of Bill Brookover, Doris Fanelli, Charles Tonetti, Todd Hart, Karen Stevens and the staff at the Lowell Conservation Center have helped guide the development of the project.

Technical assistance was provided for specialized segments of the project. Cyra Technologies provided laser-scanning services in 1999 as a demonstration of newer technologies that could be incorporated into the survey methodology in the future. The architecture firm of Dan Peter Kopple and Associates also provided support in 1999 with CAD rendering assistance and welcomed the students into their office as an impromptu on-site studio.

1.0 Introduction

Independence National Historical Park (INHP) is home to several of the most significant monumental public buildings of the early American republic. Three of these buildings, the First Bank of the United States (1795-97), the Second Bank of the United States (1818-24) and the Merchant's Exchange (1832-33), span a period when Philadelphia served as the nation's capital, and then as its financial and cultural center. Reflective of this history, these three buildings physically embody and communicate the wealth and promise of the new nation through their developed academic neo-classicism and then unprecedented use of monumental masonry construction with local stone resources. The preservation of these buildings as architectural icons of American federalism and finance was formally recognized with the establishment of Independence National Historical Park in 1959.

The increasing importance of monumental masonry construction in establishing the various styles and modes of American building began in the early nineteenth century with the revival of Greek classicism. White marble, cut and assembled to evoke the architectural prowess of the ancients, was promoted as the material of choice. The massive and easily accessible beds of Pennsylvania marble, also known as Pennsylvania Blue or Montgomery County marble, quarried just north of the city, was an important regional building stone for public and domestic structures during the first half of the nineteenth century. Benjamin Latrobe's Bank of Pennsylvania (1798-1801, demolished c.1870) and William Strickland's Bank of the United States (1818-1824) (Fig. 1) were among the first monumental stone structures to showcase the area's famous marble. On May 8, 1811, Benjamin Latrobe delivered an anniversary oration before the Society of Artists of the United States in Philadelphia, extolling the importance of the city's precious marble resources:

The beautiful marble with which this neighborhood abounds, and the excellence of all other building materials, give to Philadelphia great advantages in this branch of the fine arts. The first building in which marble was employed as the principal material of its front, is the Bank of the United States...Only one year after its completion the Bank of Pennsylvania was built...such a building so different from all that had preceded it in form, arrangement, construction, and character...[that] the style of this single building has given to the Philadelphian architecture, even in our plainest brick dwellings, a breadth of effect and response vainly sought in other cities.

By the middle of the nineteenth century, poor performance of the stone and improved transportation systems that increased the availability of other marbles from Maryland, Massachusetts and Vermont all contributed to the demise of Pennsylvania marble as a building stone. Once a building stone acquires a record of poor weatherability and is no longer commercially viable, there usually is little motivation for continued use of the material. In most cases, it is only years later through renewed conservation studies of deterioration and treatment

of historic buildings that information about the properties and performance of specific building materials and technologies is updated or reevaluated. In the case of Pennsylvania marble, its short-lived fame and restricted use have resulted in limited scientific study of its deterioration and conservation.

In December 1994, in response to observed stone failure at the Second Bank of the United States, a preliminary assessment of the exterior masonry and characterization and analysis of the stone was initiated by the National Park Service (INHP) and conservator Virginia Naudé. This led to temporary protection and emergency stabilization of critical areas of the entablature for public safety. Historically there has been periodic dimensional loss of the marble through spalling on the columns and along the entablature. Additionally, in unsheltered areas of the ashlar walls, many stones display a deep pattern of loss through contour scaling of the stone faces. (See Section 3.0 – Construction and Conservation History)

In 1996 the Architectural Conservation Laboratory (ACL) of the University of Pennsylvania in conjunction with Independence National Historical Park (INHP) began a program of stone characterization and physio-mechanical testing of potential consolidation methods for the Pennsylvania Blue marble.¹ In 1999 following these initial studies, a multi-phased conservation plan was developed and initiated with the Park beginning with the preparation of a detailed CAD-based survey of the exterior masonry conditions and the compilation of a history of past repairs and treatments to the building.² Phase 1 of the survey began with the north and west elevations in 1999. Also during this period, preservation staff from the Northeast Cultural Resources Center Building Conservation Branch of the National Park Service executed pilot mortar repairs. The exterior masonry conditions survey was brought to completion during Phase 2 of the project, surveying the south and east elevations in 2003. Presently, all of the exterior masonry has been carefully inspected and the conditions recorded, digitized drawings produced, and preliminary assessments formulated. Data gathered from the exterior masonry survey will be used in preparation for GIS-based diagnostic assessment and remedial and preventive intervention, beginning with the portico columns.

The National Park Service now has the opportunity to provide the most comprehensive research on Pennsylvania marble and its conservation due to the prominence of these three monumental buildings at Independence National Historical Park. While each building possesses distinct conditions that must be recognized individually, there is much that can be gained by addressing the full range of variations in the use, performance, and weathering of the marble and by comprehensively surveying and cataloguing the conditions across all three buildings. In addition,

¹ Jocelyn Kimmel. "Characterization and consolidation of Pennsylvania blue marble, with a case study of the Second Bank of the United States, Philadelphia, PA" (master's thesis, University of Pennsylvania, 1996).

a wider testing program can be implemented to evaluate treatments, repairs and preventive measures to address existing damage and minimize future marble deterioration and loss, and to predict areas of the stone predisposed to future failure. This program, named **The Pennsylvania Blue Project**, has the potential of providing much needed information on the history, use, properties, deterioration and treatment of Pennsylvania marble as used in thousands of buildings found throughout the city and surrounding region.



Figure 1: North Elevation of the Second Bank of the United States, April 2004.

² Report compiled by Frank Matero, Dawn Melbourne and James Toner. "Construction and Conservation History of the Second Bank of the United States," 1996, Historic Architect's File, INHP.

2.0 Project Overview

2.1 Phase 1 (1999)

The development of a conservation plan for the Second Bank of the United States will require several phases of research and investigation (some already completed) including archival documentation, condition survey and recording, laboratory and field analysis, and testing of proposed treatment interventions. Components of this research have been underway since 1986; however, Phase 1 of exterior conditions recording began with a detailed survey of the marble masonry of the north portico and façade (the main entrance to the Second Bank from Chestnut Street), and the full west elevation. The survey was conducted from June 7 through July 16, 1999. A total of six graduate and post graduate interns from the Architectural Conservation Laboratory of the Graduate Program in Historic Preservation at the University of Pennsylvania conducted a complete investigation of both elevations with the use of movable scaffolding and 60' and 45' high lift cranes with extending booms.

Rather than recording all surfaces with rectified photographs to survey conditions, the existing Historic American Buildings Survey (HABS) drawings from a 1939 survey were digitized and refined. The dimensions of architectural features and joint lines were verified in the field and corrected or added as needed. Once the coursing and stone dimensions were finalized, the base drawings were used to record detailed conditions of the masonry. Only critical areas that displayed complex deterioration patterns (e.g. column drums) were digitally photographed during the survey for later comparison.

Teams alternated between recording conditions in the field and digitizing those conditions in AutoCAD over the new drawings. During the six-week field school, all elevations of the portico including the columns, pediment, ceiling, flooring, and stairs as well as the entire west elevation were surveyed and digitized. Two interns continued for a three-week period beyond the field school to check and complete the survey drawings.

In addition to the field survey and subsequent drawings, a searchable database in Microsoft Access, a website, and report were created. For the database, each stone on the drawings was assigned a number, and each condition was entered as a separate category allowing the user to find all the conditions for any numbered stone, or to query and determine how many, or which stones have a particular condition. All conditions were eventually imported into ArcView to allow for greater diagnostic manipulation.

A complete set of digital and printed documents from this project (see Section 7 and Appendices) have been submitted to the National Park Service at INHP and the Architectural Conservation Laboratory at the University of Pennsylvania. All field notes, computer files, and correspondence have been deposited in the Archives at INHP.

2.2 Phase 2 (2003)

The exterior condition assessment was completed in 2003 with a detailed survey of the marble masonry on the south and east façades. Phase 2 of the survey was conducted from June 2 through July 11, 2003 by a total of five graduate and post graduate interns from the ACL of the Graduate Program in Historic Preservation at the University of Pennsylvania. Movable scaffolding and a 60' high lift crane with double articulated extending booms were used for recording and documentation purposes. (Fig. 3)

AutoCAD® line drawings from the 1999 survey were modified and adapted to the south and east elevations to be used as base drawings for conditions recording. The drums of the columns were accurately measured while all other joint lines on the ashlar walls, steps, and floor were carefully approximated by eye.

For surveying purposes, the team divided the conditions into five groups and assigned each group to one team member. This decision was made in order to ensure consistency across the survey in an effort to combat against the sometimes subjective nature of conditions recording despite detailed glossaries. All conditions recording of the entire east elevation and south portico including the columns, pediment, ceiling, mutules, entablature, floor, and stairs was completed during the six-week field school. Three interns continued for two to three weeks beyond the field school to begin the digitization process. One intern continued over the course of the fall and winter to complete digitization and lay out the final set of drawings.

Documentation in the form of digital photography was also made during time spent in the field. When an exemplar condition was found, it was photographed for use in the revised glossary. Unique conditions and complex deterioration patterns were also photographed, along with construction details that could only be seen with the aid of the high lift or scaffolding. (Fig. 2)

Digitization was a three-step process using Photoshop, AutoCAD, and ArcView software. First, all field drawings were scanned and rectified in Photoshop and then montages were created for each respective elevation or architectural element. The next step included importing these images into AutoCAD, where they were digitized. Scanning and montaging the field drawings

and then drawing over them using AutoCAD guaranteed the highest level of accuracy for conditions recording. CAD digitization was completed in October 2003.

While the conditions recorded in Phases 1 and 2 of the survey remained essentially the same (with some adjustment), the final drawings appear different. This is a result of the decision to use ArcView beyond its analytical capabilities; it is also useful for displaying and representing data. Not only does ArcView offer far more colors and hatches than AutoCAD, it is also easier to manipulate and fine-tune the conditions layers. With over thirty conditions represented on any given drawing, it was essential for them to be displayed in as clear and logical a manner as possible.

Using GIS as a part of the digitization process has also allowed the data to be used for future analysis of the stone's performance and deterioration. ArcView will allow an in-depth study of correlations between conditions to help determine how and why certain conditions appear in certain places over time. Eventually, the GIS software can be used to help predict where future deterioration might occur. Before any analysis can begin, however, all of the 1999 Phase 1 drawings must be ArcView compatible and therefore converted from their current AutoCAD format. Hopefully, this will occur in the near future.

Final layouts of the Phase 2 drawings were made using Adobe InDesign software and then converted into portable document files (.pdf's) with Adobe Acrobat. The final set was completed February 2004 and a complete set of the condition assessment drawings and digital files have been submitted to Independence National Historical Park. All field notes, correspondence, and digital files are also archived at the Architectural Conservation Research Center at the University of Pennsylvania.



Figure 2: A view of the capital blocks on the south elevation, July 2003.

3.0 Documentation and Archival Research

Several sources were consulted while searching for specific information on the Pennsylvania Blue marble. Research was mostly conducted at the Independence National Historical Park (INHP) office and the libraries of the University of Pennsylvania.

The majority of the information found came from the files of the Historical Architect at INHP that contain information from state Geological Surveys and student research on the Pennsylvania quarries. A ledger in the collection of INHP from the Henderson Quarry contains a balance of entries of deliveries for the construction of the Second Bank beginning April 20, 1819 and ending March 16, 1820. The first entry describes a delivery: "April 20, to 38 feet Marble delivered at the prison yard @ 140/100 foot -- \$53.20." The prison yard referred to is the Walnut Street prison formerly located one block southwest of the Second Bank; it was a prison for Tories, prisoners of war, debtors and felons used from 1775-1835. The prison was located on one of William Penn's original civic squares from Walnut Street south to Locust Street. It has not been determined whether the prison was used solely to stockpile the marble or if prison laborers provided some of the rough finishing of the marble slabs. Subsequent entries in the ledger provide dates and quantities of marble slabs delivered, but contain no additional information.

At the University of Pennsylvania, searches were conducted on Franklin, the library search system. No matches were made for any specific information on Pennsylvania Blue marble or Marble Hall or Henderson quarries in Montgomery County, Pennsylvania. Due to the time limitations of the first phase of the project, and with the emphasis on recording physical deterioration conditions, additional archival research was not conducted at other Philadelphia institutions such as the Free Library, the Athenaeum, the Historical Society of Pennsylvania or the American Philosophical Society.

At the INHP Archives, two folders entitled "Construction — Rehabilitation and Restoration / Second Bank of U.S." dated October 1964 and January 1965 contain specifications and architectural drawings for the repair work to the exterior marble columns and the platform construction around the bank (see Section 4.0). Although no documents identify exactly what repairs were done to the columns, drawings show that thru-bolts and dowels were to be driven through the columns for stabilization. Four archival boxes containing documents relating to "Construction Project Records for Second Bank Site Development, 1961-1978" were also examined at the INHP Archives. The majority of documents in these boxes, such as transmittal forms and weekly summary reports, relate to the 1971-1973 restoration of the building which consisted mostly of interior work. The documents also contain information relating to the wrought iron fencing and grates that were installed on the south façade of the building. Within these

boxes, however, one document dated October 6, 1969 written by Joe Petrak indicates that, in 1967, Hydrozo “Clearstone” was used to waterproof the exterior marble of the Second Bank. The stone was scrubbed before the treatment was applied. Another document, dated November 10, 1975 mentions re-attaching a portion of an exterior stone column with an epoxy adhesive, although no documents indicate exactly what installation methods were utilized.



Figure 3: Team member John Glavan recording conditions on the columns of the south elevation, Summer 2003.

4.0 Construction and Conservation History³

This section chronicles the construction and restoration of the exterior of the Second Bank including all past remedial interventions and maintenance. The section will start with the building's construction from 1819 to 1824 and proceed chronologically. The majority of primary sources was found while searching the Historic Building File, the Historic Architects File, and the Photographic File at the Archives of Independence National Historical Park. Most reports were located in the Historic Building File, while most correspondence was found in the Historic Architects File.

During construction the marble was quarried, cut, and dressed according to traditional stone masonry practices. Prison labor was used for sawing the marble blocks into thick veneer for the facing of the brick masonry building. Financial records indicate that saw blades and sawing sand were purchased for the task.⁴ Frame saws used for this purpose were similar to iron blade wooden saws, but without the teeth. Wet sand, used as the abrasive, was placed in a groove in the stone. The mason moved the sand back and forth with the saw blade, replenishing the wet sand as needed.⁵ The slabs were then hauled from the prison to the construction site, where the work was finished. Financial records indicate that the columns were fluted and rubbed at the construction site.⁶ The marble slabs cut for ashlar siding were also rubbed. The term "rubbing" the stone referred to honing the stone to a smooth surface with either an abrasive sandstone block or a hard rock with wet sand.⁷ Financial records show that pumice stone was purchased, which could have been used for this purpose.⁸ No documentation was found describing mortar composition, however the mortar used in 1865 was referred to as "lime cement" which indicates that lime and sand were also probably employed during the original construction.⁹

Subsequent cleaning seemed to follow traditional stone masonry methods as well. In 1844, William Strickland reported to Collector Judge Blythe that "the whole of the interior as well as the

³ Compiled by James Toner, Dawn Melbourne and Frank Matero, 1996.

⁴ Robert J. Colborn, "Historical Data," Chapter 2 of "Historic Structure Report of the Second Bank of the United States" (Philadelphia: n.p., 1962), 5, Historic Building File, INHP.

⁵ Charles McKee, *Introduction to Early American Masonry*, National Trust/Columbia University Series on the Technology of Early American Building (Washington, D.C.: Preservation Press, 1980), 5, Historic Building File, INHP.

⁶ Colborn, 5.

⁷ McKee, 30.

⁸ Colborn, 5.

⁹ Superintendent John Rier to Acting Assistant Architect B. Bertly, 26 October 1865, Historic Architects File, INHP.

exterior required a thorough cleansing and repair, particularly in the items of carpentry, masonry, painting & glazing.... The marble columns and architraves of the principle business room required scrubbing with pumice stone, to remove the dust of the years...."¹⁰ Although the use of pumice was mentioned for cleaning the interior marble, it is possible that a similar cleaning technique was used on the exterior stone as well. In 1873, Superintendent John McArthur told Supervising Architect A. B. Mullett that the Ionic carved capitols, fluted columns, molded bases, and antae were rubbed clean as part of an overall project to improve the "large room of the Custom House."¹¹ No primary source was found identifying what materials were used to clean the stone. Today, the interior marble is in good condition, with the capitals and fluting retaining good detail and little evidence of soiling.

Stone deterioration on the Bank triggered more stone repair in the early 1920's. Some loose stone was removed from the columns by 1 November 1922. The stone deterioration was considered severe enough for the federal government to request from the Obelisk Waterproofing Company of New York and the Avron Company of Philadelphia estimates for waterproofing the entire exterior of the structure. The surviving correspondence shows only the estimate from the Obelisk Waterproofing Company made in 1922.¹² The Obelisk Company gained notoriety (and its name) for applying hot paraffin wax on Cleopatra's Needle in New York City in 1885.¹³ Paraffin has a low melting point, which during hot days causes atmospheric particulates to adhere to the surface. Photographs from 1940 show the building uniformly soiled, which might be explained by the hot wax treatment.¹⁴ In 1923, Edward Crane, consulting architect, reported that several pieces of marble had fallen off, especially from the columns. He recommended that the building should be cleaned, repointed, and waterproofed. The use of a waterproof compound "could do no harm and might prove a real preservative." For cleaning, he recommended that soap and water should be applied with a stiff brush.¹⁵

The dark deposits seen in the 1940 photographs suggest cleaning was not pursued, triggering further treatment efforts. In May 1942 the exterior marble was cleaned and waterproofed, but no

¹⁰William Strickland to Collector Judge Blythe, 9 December 1844, Historic Architects File, INHP.

¹¹Superintendent of Public Buildings John McArthur to Supervising Architect for the Treasury Department A. B. Mullett, 7 January 1873, Historic Architects File, INHP.

¹² President F. S. Condit of the Obelisk Waterproofing Company to Stewardson & Page, Estimate, 31 August 1922, AIA Archives and Library.

¹³ Erhard M. Winkler, *Stone in Architecture*. 3rd edition. Springer-Verlag: Berlin, 1994. pp 182-183.

¹⁴ "Old Philadelphia Custom House" (Philadelphia: n.p., 1947), 2 Historic Building File, INHP. This phenomenon was also observed at Trinity Church, N.Y.C. around the same time period.

¹⁵ Architect Edward Crane to Supervising Architect James A. Whitmore, 16 February 1923, AIA Archives and Library.

records were found describing the reagents, tools, or methods used.¹⁶ Photographs show that the columns and the ashlar of the south façade were cleaned from the bottom up, with the northern elevation being done at about the same time in a similar pattern.(Fig. 4) The east and west façades were cleaned in sections starting at the southern and northern ends working towards the middle.¹⁷ Later reports were more complete with a 1961 report by Grant Simon recommending thirteen different methods for preserving the marble; however, no indications have been found that his cleaning recommendations were followed. Simon wanted the marble cleaned with water and brushes. More difficult areas were to be washed by hand with brushes supplemented with steam pressure at less than 100 psi. He recommended that the most difficult areas be cleaned with the previously mentioned steam pressure and by hand, supplemented with sand. After restoration, the exterior would be cleaned with water, and where necessary, scrubbed with fiber brushes on an annual basis. He discouraged the use of water repellents, detergents, or chemical solutions. Only water was to be allowed.

Marble repairs were to follow specific procedures, and some of them are familiar to contemporary conservators. He recommended the removal and repointing of all defective and loose pointing. Tapping with a light mallet would reveal any incipient spalls on the columns. (Fig. 5) Any loose or deteriorated marble on the column caps or upper horizontal surfaces could be removed and replaced with “colloidal materials,” presumably a synthetic-based composite repair. No mention was made as to exactly what materials were used. The open seams were carefully cleaned and



Figure 4: South façade, in process of being cleaned, 1942.

¹⁶ "Old Philadelphia Custom House," 2.

¹⁷ National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, May 1942.

then closed with a filler adhesive and spalled ashlar was replaced by either marble dutchmen or composite repairs.¹⁸ Today, yellow patches on the columns are visual indications that organic amended repairs were used to fill the cracks; epoxy repairs were mentioned in later records.

An August 1963 report by Gary Dysert recommended the brush application of "P-56 Brick and Stone Cleaner" after a successful test on Old City Hall. The test was conducted on twelve square feet of brick and 17.3 square feet of dressed stone at Independence Hall. The two coats were applied, left to stand for a half hour, and then washed off with water and scrubbed with a stiff bristle brush. The chemically active ingredient of the cleaner was identified as ammonium fluoride. According to the records, the 'P-56' cleaner produced a white haze on the surface. A solution of sodium bicarbonate was recommended for use to remove the residue.¹⁹ The test was judged to clean without any ill effect to either the stone or brick. There are indications that the cleaner was used on other buildings.

Some care was taken to report deteriorating exterior stone from 1964 to 1965. On 21 January 1964, a fragment of marble fell off the top of the column on the east end of the north façade.²⁰ (Fig. 6) In July 1964, Architect Joe Petrak reported that a large area of spalling on the shaft of the northwest column was clamped in place and needed "extensive repairing or partial replacement."²¹ In



Figure 5: North portico, column 1, incipient spalling. 1961.

1965, missing panels and terraces were restored to the original configuration using new marble. He also reported, "some spalling at new marble work due to hard mortar used."²²

¹⁸ Grant Simon, "Report on the Preservation of the Exterior Masonry of the Buildings" (Philadelphia: n.p., 1961), 5-6, Historic Building File, INHP.

¹⁹ Gary Dysert, "A Report on the Use of Fluoride Brick and Stone Cleaners" (Philadelphia: n.p., 1963), 1-3, Historic Building File, INHP.

²⁰ National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 21 January 1964.

²¹ Joseph Petrak, "Historic Structure Report of the Second Bank of the United States" (Philadelphia: n.p., July 1964), 17, Historic Building File, INHP.

²² Penelope Batchelor, "Census of Treated Historic Buildings" (Philadelphia: n.p., 1982), 5-7, William Brookover's File, INHP.



Figure 6: North portico, column 1, dimensional loss. 1964. Note fresh loss of upper area in 1961 photograph (Fig. 5).

The January 1964 report of spalling stone preceded the extensive restoration and conservation work performed on the Second Bank that summer. The northern and southern steps, terrace, and cast iron railing were restored to the original design of William Strickland in 1964. Architect Joe Petrak reported that "at the present time cleaning and pointing of the marble is in progress and is being done by the day-labor force. The surfaces were cleaned with fluoride solutions and clear water, and the results were satisfying."²³ Park Architect

Penny Batchelor reported that the fluoride solutions were applied with soft bristle brushes and rinsed with clear water.²⁴ Photographs taken in July and August of 1964 indicate the cleaning patterns for only the north and south façades. (Fig.7) For the north façade, the scaffolding was first erected on the eastern side of the portico. The workers started cleaning at the apex of the raking cornice and then proceeded down to the columns and ashlar stones. The scaffolding was first set up on the west side of the south façade beyond the sides of its porticoes. The pediment was cleaned from top to bottom, and then the columns and the ashlar were treated in the same manner.²⁵

On 9 March 1969, Joe Petrak reported to the Superintendent that the exterior marble treatment was completed in June of 1967. The marble was scrubbed prior to waterproofing."²⁶ Hydrozo "Clear-Stone" was then applied on the entire masonry as a water repellent.²⁷ Clear-Stone

²³ Petrak, 23.

²⁴ Batchelor, 1-2.

²⁵ National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 17 August 1964, negative # 8613, photograph by W.A. McCullough.

²⁶ Joseph Petrak to the Superintendent, Memorandum, 9 October 1969, Historic Architect Files, INHP.

²⁷ Batchelor, 5-7.



Figure 7: South portico in process of being cleaned. 1964.

contains 2 ¼% silicone solids as produced by the General Electric Co., Silicones Division.²⁸ In March 1974, Harold Heller mentioned that in the 1960's a silicate was applied to the Second Bank "which today [1974] remains quite clean. On close examination of this building, it was found that surfaces exposed to the weather are not [any longer] protected but areas such as the protected surfaces of the columns still repel water."²⁹ Traces of this water repellent still exist (See Section 8.0).

In the early 1970's, the Second Bank was rehabilitated to become the National Portrait Gallery. A museum quality HVAC system and other new internal systems were installed. Marble cleaning and repairs were carried out on both the interior and the exterior of the building during this period.

Revised specifications mentioned that new marble should have a tooled weathered surface or a rubbed sanded surface to match existing stone. New marble was used for both Dutchman repairs and new construction. Some windowsills might have been repaired in this fashion, however most appear to have been tooled with a point chisel. The Dutchman repairs were to be epoxied tightly into place in carefully cut out deteriorated sections. Specifications state what should have rather than what actually occurred.³⁰ The Historical Architect's office of Independence National Historic Park has architectural drawings that indicate where new stone-blocks were placed in the early 1940's, early 1960's, and the early 1970's building campaigns.

²⁸Penelope Batchelor, "1974-1976 Construction Phase Masonry Construction Methods Used," Appendix VI of "Historic Structure Report Historical and Architectural Data First Bank of the United States" (Philadelphia: n.p., 1981), 228, INHP.

²⁹ Harold Heller, "An Approach to the Restoration and Preservation of the First Bank," Appendix V of "Historic Structure Report of the First Bank of the United States" (Philadelphia, n.p., 1981), 206-221, INHP. Recent SEM-EDS analysis has verified the presence of silicon-based coatings on the protected portico walls.

³⁰ Denver Service Center, "Specifications Adaptive Restoration and Rehabilitation Second Bank of the United States" (Philadelphia: n.p., 1973), 4-9, Historic Building File, INHP.

Windowsills and other marble blocks that displayed damage too shallow for Dutchmen were repaired with cement mortar patches. Notes from the contract and construction negotiations describe how damaged exterior marble sills were to be built up back to their original profiles so that the water drained away. The repair material was to be Weld-crete from Larson Products Corporation in Rockville, Maryland. It was used in a "fortified topping process, which allows feather edging". One part 'Weld-crete to three parts water was specified, the Weld-crete used in place of water as an admix to the original cement mix. The final product was to match the original stone sills in color and texture. Any loose spalling layers of the stone were to be taken off before being patched.³¹ Today, there are remains of what appear to be concrete patches on the lowest south portico windows. Dense cement repairs there tend to trap any water that seeps through the protective surface, thus causing more spalling than otherwise might occur.

The interior polished marble in the main banking room was cleaned using two methods. With the first method, the marble cornice stone was cleaned with FINOLA Abrasive Scouring Powder, made by Masury Columbia Company, Melrose Park, Illinois 60160. This method was mixed with water, and the marble was scrubbed with steel wool. The powder was ineffective on the marble columns and capitols, which were cleaned with Wyandotte Detergent Powdered Abrasive Cleaner. This powder was added to a five to one mix of water and Clorox (sodium perchlorate) until a paste was made. The poultice was trowelled onto the stone, and allowed to remain on the surface for a minimum of 24 hours. Later, the poultice was washed off with clean water and a bristle brush."³²



Figure 8: Interior column capitol cleaned with a poultice. 1974.

³¹ Craig Morrison, Notes, Meeting with Mike Callaghan Marble Shop, Historic Architect's Files, INHP.

³² Penelope Batchelor, Notes, 12 December 1973, Historic Architect's Files, INHP.

A photograph taken on 2 May 1974, documented an original column capitol had been cleaned with a poultice.³³ (Fig. 8)



Figure 9: Worker cleaning spray paint vandalism. 1971.

Some marble deterioration was carefully recorded during the 1970's. In April 1971, a worker was photographed painting an unidentified cleaner onto spray paint graffiti on the north façade.³⁴ (Fig. 9) A color slide taken in September 1975 shows yellow patches on the N-2 column, indicating old epoxy repairs.³⁵ In 1975, Penny Batchelor noticed that a "rather sizable" piece of marble was on the verge of spalling off from the column next to the west of the north façade [Column 1]. "The piece is below waist level facing

northwest." She suggested that the piece could be secured "with an epoxy glue used for stone repairs" on the First Bank at the west doorframe.³⁶ The epoxy used for the east façade for the First Bank was 10% Epi-rez 510 made by Celanese Coatings, Inc. in Louisville, Kentucky. The solvent was methyl ethyl ketone, and the mixing standards were followed according to United States Patent No. 3,795,533.³⁷ It is not clear if this treatment was executed.

Records made during the 1980's and 1990's document the deterioration of the marble, the location of some of the minor repairs, and the maintenance practices of the period. The building sustained damage from both vandalism and stone decay. One photograph taken in November 1983 shows that pigeon guano stained the marble as well as "Roost-NO-More" pigeon control.³⁸ On 15 July 1985, Bill Brookover inspected scratched graffiti with "the words `George W. 1776`

³³ National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 2 May 1974, negative # 157.4315.32, photograph by Eisenman.

³⁴ National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, April 1971, negative #10307A, photograph by W.A. McCullough.

³⁵ Color Slide, September 1975, William Brookover's File, INHP.

³⁶ Penelope Batchelor to Superintendent of INHP, Memorandum, 10 November 1975, Historic Architect's File, INHP.
Note: Only dimensional loss is recorded on the described location on the 1999 condition assessment drawings. Therefore, the repair was either not made or failed.

³⁷ Penelope Batchelor, "1974-1976 Construction Phase Masonry Conservation Methods Used," Appendix VI of "Historic Structure Report First Bank of the United States" (Philadelphia: n.p., 1981), 227, INHP.

³⁸ William Brookover Photograph, 1986, William Brookover's File, INHP.

carved into a column" in the north portico, designated N-4 by the Naudé report. The graffiti was lightly scratched into the marble surface and could be easily removed using soft bristle brushes and water.³⁹ Scratched graffiti is currently visible on several columns on the north and south façades. A few fragments of marble fall from the building every few years. On 7 October 1986, John Kornich found a piece of fallen marble on the west end of the north portico, probably from the cornice.⁴⁰ On 28 April 1989, two pieces of marble were found at the south façade in the alley way and on the porch near the S-1 column.⁴¹

Only small-scale repairs were conducted in the 1980's and 1990's. On 8 May 1986, a small fragment of marble was readhered with epoxy on column S-2, as designated by the Naudé Report.⁴² (Fig. 10) The type of epoxy was not recorded. From 1983 to the present, several fragments of marble had fallen off and were epoxied back in place by a stonemason, without any documentation. During the same time period, a mason installed Dugan limestone patches with a polymer-bonding agent. To prepare a patch, the shallow areas of the damaged stone were cut away with a four-inch diamond blade to insure a good key.⁴³

Recent maintenance procedures may be equally problematic to accurately document. For example, the pigeon guano was "cleaned" with city water on the north and south portico paving. The dirty rinse water washed down the steps and over the west edge of the portico. As a result, the guano was deposited on the stair risers, the west wall of the portico, and the terrace-paving wall.⁴⁴ Today, dark deposits near the bottom of the north and south portico ashlar indicate that dirty water also splashed



Figure 10: South portico, column 2, marble epoxy repair. 1986.

³⁹ William Brookover to General Foreman Ross Flanagan, Memorandum, 13 August 1986, Bill Brookover's File, INHP. 38.

⁴⁰ John Kornich, Report to Historic Architects, 7 October 1986, Bill Brookover's File, INHP

⁴¹ Report to Historic Architects, 28 April 1989, Historic Architect's File, INHP.

⁴² National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 8 May 1986, photograph by William Brookover.

⁴³ Stone Mason Frank Doyle, Conversation with Author, August 1995.

⁴⁴ William Brookover to Ross Flanagan, Memorandum, 13 August 1986, William Brookover's File, INHP.

against the portico walls and columns. Bird guano can introduce both phosphate and nitrate salts into the marble as well.⁴⁵ Recently, calcium chloride was the preferred deicing salt for the steps and walkways of the Second Bank, thus introducing chlorides into the marble.⁴⁶

More attention has been paid to the building recently. Bird netting was installed around the pediment during March 1994, which reduced pigeon access and guano.⁴⁷ In November 1999, a piece of the cornice fell; and in response, bird netting was installed around the projecting cornice. In December 1994, Virginia Naudé and Bill Brookover inspected the exterior marble over two days. She advised that immediate repairs should be confined to the traditional mortar or marble repairs until more complex treatments are thoroughly tested."⁴⁸

In conclusion, the Second Bank was built and repaired using traditional methods and materials during the early nineteenth century. There were three exterior cleaning and waterproofing campaigns performed on the building in the twentieth century. Around 1922 to 1923, the building was cleaned with soap and water and probably waterproofed with hot paraffin wax. The second cleaning and waterproofing treatment occurred in 1942 but without any mention of any of the compounds or the methods used. In 1964, the exterior marble was cleaned with aqueous fluoride solutions (possible P-56 Brick and Stone Cleaner) and waterproofed with a silicate, Hydrozo "Clearstone." Reports of marble deterioration preceded the 1923 and the 1964 treatments. Minor mortar and epoxy repairs as well as Dutchmen were performed at intermittent times in the twentieth century, often after marble spalled. Not all of the repairs and patches were recorded. In 1996 as part of a long-range conservation program for the exterior masonry, the Architectural Conservation Laboratory of the University of Pennsylvania began a renewed program of stone analysis, treatment testing, and masonry conditions survey.

⁴⁵ Erhard M. Winkler, 230.

⁴⁶ William Brookover Commentary on Memorandum from District Ranger to Safety officer, 30 January 1992, William Brookover's File, INHP.

⁴⁷ William Brookover, Conversation with Author, 30 August 1995.

⁴⁸ Naudé, Virginia. "Survey of Exterior Marble, Second Bank of the United States, Philadelphia, PA." 1994, 18-19.

5.0 Marble Decay: An Overview

In developing a conservation program for any masonry building, a variety of factors must be considered including the age and history of the building, the chemical composition and mechanical properties of the stone, the nature of its decay mechanisms, and the rate of deterioration relative to building location and environment.

Marble is a carbonate-based metamorphic rock which like most building stones, will undergo alteration and decay from a wide range of factors including pollution and freeze-thaw, salt, and thermal cycling. The mineralogical composition and grain structure of each type of marble will ultimately determine how vulnerable it is to decay from weathering. While all marbles are susceptible to chemical dissolution from acidic agents, the texture and fabric of the rock will dictate to a large degree its specific response to weathering. Degree of foliation, presence of secondary minerals such as micas, graphite and pyrite, and grain size and shape will all affect its durability. Mechanical damage, often indicated by cracking, will result by overloading the cohesive grain-to-grain strength of the marble.

The original stone of the Second Bank is of two varieties: a coarsely crystalline creamy white marble and a light blue banded or mottled marble. Both are interbedded with dark blue to black siliceous dolomite. The marble is weakly metamorphosed and contains abundant micaceous inclusions and the calcite is not strongly recrystallized. The marble is loosely textured, with a marked foliation (or planar) fabric forming a series of parallel planes that are weakly held together. The dominant mineral is light blue calcite grains ranging in size from 100-400 microns, angular to sub-rounded in shape and nearly of pure calcium carbonate. There are also small amounts of magnesium and iron.⁴⁹

Mechanical damage can occur in several ways. Columns and other supports can crack by tensile, compression or shear forces while smaller architectural elements can fail from traffic or construction vibrations. Long-term stresses cause plastic deformation or creep. More dramatic damage can occur from blasting or seismic shock. Quarry blasting is often used to extract rock for construction. The explosion triggers a stress pulse that the rock can absorb and store. As the pulse pressure lessens, the internal stresses are released by stone fragmentation and microcracking. The resultant cracking and spalling provide moisture and salt entry causing greater damage.

⁴⁹ Elaine S. McGee. "Marble Characteristics and Deterioration." In *Philadelphia Merchants' Exchange Conservation Strategy. Environmental and Cultural Resources Research Monograph No. 1* (Washington, D.C.: National Park Service, 1992), 13.

Salt crystallization is considered potentially one of the most damaging mechanisms to stone buildings, especially when a building is in a climate prone to frequent wet-dry cycles. Salt crystallization begins when salts are dissolved in water and are transported through the pores of the stone. Salts can also be deposited on the surface from the atmosphere, evaporating groundwater, or contaminants such as bird guano, cleaning treatments, and deicing salts. Precipitated surface salts, or efflorescence, cause less damage than those crystallizing within the pores of the stone. Such subflorescence can exert sufficient internal disruptive pressure to overcome the grain-to-grain cohesive strength of the stone matrix. The amount of damage depends on many factors: most notably the species and combination of salts, the microclimate, and the porosimetry of the stone. Moreover, the presence of salts promotes condensation and rising damp which escalates the entire process. Most marbles are fairly dense with porosities of one percent or less; however as the grains become detached from internal mechanical stresses, porosity can increase deterioration.

Acidic attack from dry and wet deposition or from inappropriate acidic cleaning will dissolve the calcite and dolomite matrix and form gypsum crusts. Secondary mineral inclusions such as pyrite can accelerate this decay by producing sulfuric acid, which can also convert the calcite to gypsum. The formation of gypsum distorts surface details and is more vulnerable to loss as it is 25 times more soluble than calcite and its expansive structure is weakly attached to the unaltered stone substrate. The presence of expansive clay secondary minerals can also swell and produce mechanical stresses in the stone when wet or erode away more easily than other less water-sensitive inclusions. Carbon dioxide in rainwater forms carbonic acid, which over time converts calcium carbonate to soluble calcium bicarbonate.

The weathering of crystalline marble is a complex interaction of several decay mechanisms and varies according to the particular structure and composition of the marble as well as its orientation in the building. The surface of the Pennsylvania Blue marble is vulnerable to surface weathering (i.e. disaggregation) because its calcite structure is weakly metamorphosed with poorly interlocking grain boundaries, and it has a large percentage of inclusions. Dimensional expansion-contraction and chemical dissolution of the calcite grains start the release of locked-in stresses by the anomalous thermal behavior of calcite, and by the expansive action of trapped moisture. Dilation occurs resulting in crumbling and cracking of carved details and edges. Disaggregation (friability) and flaking are the first indications of surface erosion and dissolution. Wet marble exhibits lower strength and hardness and dry climate conditions trigger evaporation that transports soluble calcite to the stone surface and leads to case-hardening. Freeze-thaw cycling exacerbates loss of the case-hardened surface and causes flaking and contour scaling, especially where the foliation of the marble is parallel or oblique to the surface. Thermal cycling and its associated mechanical cracking are most prevalent on the columns and especially on the

column fluting. Thermal expansion of calcite is not uniform. When heated, the calcite crystal expands along the long axis but contracts along the short axis. Spalling is triggered by the same mechanisms as cracking, but the internal stresses are relieved when parts of the stone detach in concentric “spalls”. Severe spalling on the rear face of the columns of both porticos suggests other factors may also be at play. The presence of heavy black gypsum crusts in these areas, attributable to the lack of rain water washing, may be exacerbating detachment by the crystallization of gypsum in the microcracks. In summary, cracking and grain loss occurs when internal stresses from metamorphism are released during quarrying, stone working, diurnal and seasonal thermal expansion, or by moisture expansion. Cracking occurs at grain boundaries and boundaries between the calcite and weaker secondary minerals. (Fig. 11)

The specific deterioration of both types of Pennsylvania Blue marble at the Second Bank must be studied in greater detail to establish a hierarchy of decay mechanisms affecting the building overall or in specific locations based on stone type, orientation, environment and microclimate, and previous treatment.




Figure 11: Existing conditions on the columns of the south elevation. Summer 2003.

6.0 Existing Conditions

6.1 Condition Recording and Assessment: A Conservator's Guide

The idea of a procedurally rigorous survey of field conditions, including the integration of various forms of information (e.g., construction and maintenance records, existing photographs, environmental data, etc.) and various methods of recording, for the purposes of **diagnostic** assessment of a building including its fabric and systems, has been an important step in developing both accurate and holistic approaches to building and site conservation. Such field surveys force the building conservator to account for every possible **etiological** relationship between material, construction, design, environment, use, and maintenance, through the detailed recording of conditions in the present and over time. By recording condition in conjunction with other physical aspects of a structure or site during the initial phases of documentation, and by considering what such conditions mean throughout a project, the condition survey becomes a powerful diagnostic tool for answering a range of research questions ultimately concerned with design, performance, alteration, treatment, and maintenance.

Through the development of clearly defined, causal-free terminology based on a descriptive recording of observed **symptoms**, the condition survey can at once document the type, extent, location, pattern, severity (degree) and status (active/inactive) of observable **phenomena**. Past conditions may also be recorded using historical images and detailed descriptions when available. In so doing, and in conjunction with other data sets (such as compositional analysis, use and maintenance history), condition recording assists in the explanation of decay mechanisms, as well as providing diachronic **evidence** for the construction, use, and repair or neglect of the building and site.

A symptomatic recording of conditions attempts to describe what one sees at time present according to physical appearance. A condition survey usually occurs at one brief moment in the life of the structure or site, yet a structured approach to the evidence – visible and invisible – allows a temporal reading of what was, is, and will or might be. Causal explanation can then follow based on a reading of site evidence along with associated environmental and structural monitoring, material analysis, historical research, etc. Even without archival images of past conditions, a detailed survey of current conditions can trace the physical progression of weathering through relative time by way of shifting patterns, extent, severity, or even type transformation of decay such as disaggregation into scaling or flaking and eventually loss.

Since immediate and ultimate causes may be open to several interpretations, it is imperative that the survey be as accurate and free from assumptions as possible. However it is also important to realize that the act of interpretation begins the moment the recording process occurs, if only by its selecting of conditions chosen for observation.

Conditions are the incidental residual result of events and processes. Conditions, like stratigraphic deposits, are a by-product of many factors: use, aging, neglect, repair -- the whole array of human and natural factors. If conditions are recorded as evidence, a more accurate account of cause/effect relationships can be established and appropriate interventions conducted. The built environment, like its natural geological counterpart, is a collection of unique outcomes at once constantly changing through differential weathering, yet similar in the predictability of the natural entropic and anthropic processes responsible for the change. This obvious yet important observation reinforces the role condition surveys can play in identifying the unique combination of factors responsible for material change. Despite the fundamental information condition surveys provide on the type and extent of material damage and the diagnosis of material and building failure, there exists a general lack of coordinated recording standards in architectural conservation. To this end, a detailed, illustrated condition glossary was developed for the marble of the Second Bank (Appendix C).

- **DIAGNOSIS** - The conclusion reached by detailed analysis. (Greek-to discern, literally to perceive apart)
- **ETIOLOGY** - The study of causes, origins, reasons. The cause of a disorder as determined by diagnosis
- **EVIDENCE** – The data on which a judgment or conclusion may be based, or by which proof or probability may be established, present and plainly visible, clear, obvious (Latin-*evidens*-to see completely)
- **PHENOMENA** – An observable event or occurrence that is directly perceptible by the senses (from the Greek-to appear or show).
- **SYMPTOM** – Any circumstance or phenomenon regarded as an indication or characteristic of a condition or event; a departure from normal appearance.

6.2 Conditions Recorded: Phase 1

A detailed glossary of conditions was developed and tested for the field survey of the marble of the north portico and west elevation. Several goals were defined that led to the final identification and classification of conditions:

- **Only after completely mapping conditions and understanding the broader deterioration patterns can more specialized types of analysis be utilized to explain cause-effect relationships.**
- **Conditions recorded were classified according to severity and degree or type of action required.**
- **The conditions recorded included inherent compositional defects within the stone, the influence of weathering conditions in the surrounding environment (temperature, moisture, structural and thermal stresses, accumulation of airborne pollutants), previous repairs, and historic loss. In this way, patterns of decay can be studied over time and in combination with former repairs and maintenance.**
- **The glossary should be adaptable to other buildings within INHP, particularly the First Bank and Merchant's Exchange so that marble conditions and data can be compared across a wider spectrum of case studies.**

6.3 Conditions Recorded: Phase 2

The glossary of conditions developed during Phase 1 of the survey was used as a basis for Phase 2. After careful study in the field, however, several major and minor modifications were made to some condition definitions. The following table indicates those conditions with definitions which were **moderately** changed:

Condition	Definitions	
	1999	2003
Orientation of Foliation Planes		addition of "face-oriented" stones
Moderate Cracks	less than 1/8"	1/16-1/8"
Deteriorated Mortar Joint	mortar present in joints is friable	mortar present but eroded back 1/2" or more in depth
Dimensional Loss	4"sq., 1" deep	2" sq., 1/2" deep
Stone Redressing	did not exist	added
Surface Unique	did not exist	added

It is of utmost importance to notice two **major** changes concerning the definitions of *differential (surface) erosion* and *contour scaling*. These conditions occur frequently on all façades of the Second Bank and play a significant role in the building's deterioration patterns. While their specific definitions can be read in the glossary, the most important difference between the 1999 and 2003 definitions is that what was recorded as *surface erosion* in 1999 was identified as *flaking* in 2003. It was also determined that the description used to define *surface erosion* in 1999 is better characterized as *differential erosion*. The second major change to the conditions glossary was the re-working of the definition of *contour scaling*. The Phase 2 team ascertained that *contour scaling* is, in essence, *flaking* to a greater extent and so modified the definition to reflect this change.

Aside from the definitions, the classifications of the conditions were also changed. Phase 2 conditions were grouped according to whether they were *subtractive* or *additive*. All other conditions were categorized as *other*. Colors used were based on and represent these groupings.

The 2003 glossary was also updated with new photographs taken by team members in the field.




Figure 12: Working from the high-lift on the south elevation, summer 2003.

7.0 Condition Assessment Drawings

DEFINITION GRAPHIC SCHEMATIC

Orientation of foliation planes

Stones display a pattern of orientation based on their foliation planes. For edge-oriented stones, the position of these planes can be (a) horizontal, (b) vertical or (c) diagonal to the ground. For face-oriented stones, foliation planes are (d) parallel to the face of the stone.



Mineral inclusions

Stones may display large mineral inclusions as veins or phenocrysts. These inclusions are at least 1/2 inch in diameter and noticeably larger than prevailing foliation patterns. They are typically (a) raised in relief or (b) weathered out and distinctive in color and texture from the surrounding stone matrix.



Network cracking

A patterned network of fine intersecting cracks occurring on the surface of the stone, often in association with mineral inclusion-rich areas.




Moderate cracks

Cracks that are 1/16-1/8 inch (1.6-3.2 mm) wide, of varying orientation and depth. These can be either (a) structural or (b) those that occur along foliation planes.



Major cracks

Cracks greater than 1/4 inch (3.2 mm) wide, of varying orientation and depth. Usually associated with (a) deformation / displacement or (b) incipient spalling.




Friability / Flaking

Surfaces with (a) active disaggregation of individual grains and / or (b) shallow flakes that dislodge under finger pressure.




Differential erosion

Surface weathering defined by (a) large areas of coarse texture, (b) localized loss greater than 1/4 inch in depth (e.g. along foliation planes), or (c) reduction of surface details (e.g. weathered arrises or edges).



Contour scaling / Exfoliation

Distinctive localized or overall patterns of stepped irregular surface loss associated with cracks and foliation planes, and the loss is greater than 1/4 inch in depth.



DEFINITION GRAPHIC SCHEMATIC

Incipient spalling

Surface planar discontinuities that have become partially separated from the parent stone. The detached area can be detected visually and audibly by sounding. The angle of separation will be approximately 0-60° from the surface plane of the surrounding stone and usually in association with foliation.



Dimensional loss

Localized stone loss greater than 2 square inches in area and at least 1/2 inch in depth as measured in plane with the surrounding stone surface.



Deformation / Displacement

Movement and cracking or separation of the stone or stones resulting in the shifting of stone surfaces more than 1/4 inch out of plane. Relative planar shifts recorded as (+) or (-).



Open joints

Stone joints where the pointing mortar is completely lost.



Deteriorated mortar joint

Stone joints where the mortar is still present but eroded back 1/4 inch or more in depth, or noticeably cracked and partial.



Efflorescence

White crystalline, water-soluble deposits on the surface or within the pores of the stone indicating the presence of damaging salts.



Metallic staining

Localized discoloration resulting from the weathering of either (a) intrinsic (mineralogical) or (b) extrinsic (copper or iron accessories) sources, usually black/brown (iron) or blue/green (copper) in color.



Encrustation

Formation of gray to black particulate deposits in protected areas that are noticeably more concentrated than the prevailing soiling patterns.



Microflora

Zones of biological growth including algae, fungi, and lichens visible as a black, greenish or brown discoloration. Many of these areas are on the lower sections of the building, under windowsills, and along the cornice area at the tree line.



GLOSSARY OF MASONRY CONDITIONS

SECOND BANK OF THE UNITED STATES INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA

<p>PROJECT SUPERVISORS: FRANK MATERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p> <p>PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>	<p>SPONSORED BY: PARK SERVICE CAMDEN OFFICE INDEPENDENCE NATIONAL HISTORICAL PARK PHILADELPHIA, PA 19106</p>
<p>CONDITION ASSESSMENT: JOHN GLAVAN LAUREN HEGERTY JOHN HOWARD</p>	<p>CONTRIBUTORS: KERRY JOHNSTON SOPHIA MIDDLEBROOK</p>
<p>THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA</p>	
<p>SITE RECORDING: SUMMER 2003 DATA INPUT: FALL 2003</p>	

DWG CS-1

DEFINITION GRAPHIC SCHEMATIC

Chemical bird repellent treatments

Residue of chemical gels and coatings used on horizontal surfaces to deter birds from landing and nesting on the building.



Sealant repair

Presence of elastomeric sealants used as a masonry repair or pointing material.




Repointing

All non-original mortars used for repointing joints, usually gray or white in color.



Stone dutchman

Stone infill repair (a) set into the surrounding masonry, with or (b) without associated adhesive or mortar.




Filled cracks

Repairs to cracks executed at any time:

(a) less than 1/4 inch in width.



(b) greater than 1/4 inch in width.



Tooling marks

Stones that are relatively protected still display their original surface tooling marks. The tooling marks are a relative indicator of the degree of surface weathering of the stone. The condition was recorded only where the tooling is evident on at least 50% of the stone's surface.



Composite repairs

A mortar or resin based system, used as a surface repair for losses greater than 3/4 inch in width but not for cracks.



DEFINITION GRAPHIC SCHEMATIC

Stone replacement

Physical and/or archival evidence that complete stones or sections of the building, terraces, or perimeter walls have been replaced. Include date if known.



Previous coatings

The presence of a coating on the stone surface, generally off-white or pale yellow in color.



Stone redressing

Tooling marks that indicate the selective redressing of stone to address advanced surface deterioration.



Defective mechanical features

Building systems and/or anchoring hardware that is contributing to a stone deterioration condition.



Condition - unique


Any condition or physical alteration to the original fabricated surface of the building which does not fit within the existing set of categories. Numbering is sequential but does not reflect a specific order to the conditions.



(3) Spall fallen and collected

Historic conditions

Historic photographs that provide a time-based comparison of stone loss, weathering, and soiling patterns.



page 2/2

GLOSSARY OF MASONRY CONDITIONS



SPONSORED BY: PARK SERVICE
CAMDEN OFFICE
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106

PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

CONDITION ASSESSMENT BY: KERRY JOHNSTON, SOPHIA MIDDLEBROOK, JOHN GLAVAN, LAUREN HEGERTY, JOHN HOWARD

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA




SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA
 PROJECT SUPERVISOR:
 FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
 PROJECT MANAGER:
 JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

SPONSORED BY:
 NATIONAL HISTORICAL PARK SERVICE
 CAMDEN OFFICE
 INDEPENDENCE NATIONAL HISTORICAL PARK
 PHILADELPHIA, PA 19106

CONDITION ASSESSMENT:
 JOHN GLAVAN
 LAUREN HEGERTY
 JOHN HOWARD
 KERRY JOHNSTON
 SOPHIA MIDDLEBROOK

SITE RECORDING: SUMMER 2003
 DATA INPUT: FALL 2003



SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA

EAST ELEVATION
 NORTH HALF

PROJECT SUPERVISOR:
 FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

PROJECT MANAGER:
 JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN



SPONSORED BY:
 CAMPAIGN OFFICE
 INDEPENDENCE NATIONAL HISTORICAL PARK
 PHILADELPHIA, PA 19106

CONDITION ASSESSMENT:
 JOHN GLAVAN
 LAUREN HEGERTY
 JOHN HOWARD

SITE RECORDING: SUMMER 2003
 DATA INPUT: FALL 2003

KERRY JOHNSTON
 SOPHIA MIDDLEBROOK

DWG 102



SECOND BANK OF THE UNITED STATES

INDEPENDENCE NATIONAL HISTORICAL PARK
 PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
 PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

SPONSORED BY: PARK SERVICE
 CAM OFFICE
 INDEPENDENCE NATIONAL HISTORICAL PARK
 PHILADELPHIA, PA 19106


CONDITION ASSESSMENT:
 JOHN GLAVAN
 LAUREN HEGERTY
 JOHN HOWARD

KERRY JOHNSTON
 SOPHIA MIDDLEBROOK

SITE RECORDING: SUMMER 2003
 DATA INPUT: FALL 2003

DWG 103

EAST ELEVATION
 SOUTH HALF





SOUTH ELEVATION

SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA

<p>PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>	<p>SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE CAMDEN OFFICE INDEPENDENCE NATIONAL HISTORICAL PARK PHILADELPHIA, PA 19106</p>	<p>CONDITION ASSESSMENT: JOHN GLAVAN LAUREN HEGERTY JOHN HOWARD</p>
<p>PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>		<p>SITE RECORDING: SUMMER 2003 DATA INPUT: FALL 2003</p>
<p>THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA</p>		<p>KERRY JOHNSTON SOPHIA MIDDLEBROOK</p>
		<p>DWG 104</p>

CONDITIONS LEGEND

- Open Joint
- Deteriorated Joint Mortar
- Major Crack
- Moderate Crack
- Network Map Cracking
- Friability/Flaking
- Contour Scaling
- Differential Erosion
- Incipient Spalling
- Dimensional Loss
- Filled Crack Less Than 1/4"
- Filled Crack Greater Than 1/4"
- Repointing
- Chemical Bird Repellent
- Treatment Coating
- Stone Redressing
- Stone Dutchman
- Stone Replacement
- Composite Repair
- Sealant
- Intrinsic Metallic Staining
- Extrinsic Metallic Staining
- Non-Intrinsic Staining
- Microflora
- Efflorescence
- Encrustation
- Deformation/Displacement
- Mineral Inclusion
- Defective Mechanical System
- Railing Remnant
- Foliation Orientation



**EAST ELEVATION
SOUTH HALF**

**SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA**

SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE
CAMDEN OFFICE
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106


PROJECT SUPERVISOR: FRANK M. ATERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

CONDITION ASSESSMENT:
JOHN GLAVAN
LAUREN HEGERTY
JOHN HOWARD

KERRY JOHNSTON
SOPHIA MIDDLEBROOK

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

DWG 105



CONDITIONS LEGEND

- Open Joint
- Deteriorated Joint Mortar
- Major Crack
- Moderate Crack
- Network Cracking
- Friability/Flaking
- Contour Scaling
- Differential Erosion
- Incipient Spalling
- Dimensional Loss

- Filled Crack Less Than 1/4"
- Filled Crack Greater Than 1/4"
- Repointing
- Chemical Bird Repellent
- Treatment Coating
- Stone Redressing
- Stone Dutchman
- Stone Replacement
- Composite Repair
- Sealant

- Intrinsic Metallic Staining
- Extrinsic Metallic Staining
- Non-Intrinsic Staining
- Microflora
- Efflorescence
- Encrustation
- Deformation/Displacement
- Mineral Inclusion
- Defective Mechanical System
- Railing Remnant
- Foliage Orientation

**EAST ELEVATION
NORTH HALF**

**SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA**

PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
 PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

SPONSORED BY: PARK SERVICE
 CAM OFFICE: INDEPENDENCE NATIONAL HISTORICAL PARK
 PHILADELPHIA, PA 19106


CONDITION ASSESSMENT: KERRY JOHNSTON, SOPHIA MIDDLEBROOK
 JOHN GLAVAN, LAUREN HEGERTY, JOHN HOWARD

SITE RECORDING: SUMMER 2003
 DATA INPUT: FALL 2003


DWG 106

**ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA**

PEDIMENT AND EXTERIOR ENTABLATURE FACE




INTERIOR ENTABLATURE FACE



CONDITIONS LEGEND

- | | | |
|---|--|--|
| <ul style="list-style-type: none"> Open Joint Deteriorated Joint Mortar Major Crack Moderate Crack Network Map Cracking Friability/Flaking Contour Scaling Differential Erosion Incipient Spalling Dimensional Loss | <ul style="list-style-type: none"> Filled Crack Less Than 1/4" Filled Crack Greater Than 1/4" Re-pointing Chemical Bird Resellent Treatment Coating Stone Redressing Stone Dutchman Stone Unit Replacement Composite Repair Sealant Foliage Orientation | <ul style="list-style-type: none"> Intrinsic Metallic Staining Extrinsic Metallic Staining Non-intrinsic Staining Microflora Efflorescence Encrustation Discoloration/Displacement Mineral Inclusion Defective Mechanical System Railing Remnant |
|---|--|--|



**SOUTH PORTICO
PEDIMENT AND ENTABLATURE**

**SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA**

SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE
FIELD OFFICE: INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106


PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

CONDITION ASSESSMENT:
JOHN GLAVAN
LAUREN HEGERTY
JOHN HOWARD

KERRY JOHNSTON
KERRY JOHNSTON
SOPHIA MIDDLEBROOK

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

DWG 107



CONDITIONS LEGEND

- Open Joint
- Deteriorated Joint Mortar
- Major Crack
- Moderate Crack
- Network Map Cracking
- Friability/Flaking
- Contour Scaling
- Differential Erosion
- Incipient Spalling
- Dimensional Loss

- Filled Crack Less Than 1/4"
- Filled Crack Greater Than 1/4"
- Repointing
- Chemical Bird Repellent
- Treatment Coating
- Stone Redressing
- Stone Dutchman
- Stone Replacement
- Composite Repair
- Sealant

- Intrinsic Metallic Staining
- Extrinsic Metallic Staining
- Non-Intrinsic Staining
- Microflora
- Efflorescence
- Encrustation
- Deformation/Displacement
- Mineral Inclusion
- Defective Mechanical System
- Railing Remnant
- Foliage Orientation

**SOUTH PORTICO
REAR WALL**

**SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA**





SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE
PROJECT MANAGER: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

CONDITION ASSESSMENT BY: KERRY JOHNSTON, JOHN GLAVAN, LAUREN HEGERTY, JOHN HOWARD
SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

INDEPENDENCE NATIONAL HISTORICAL PARK
CAMDEN OFFICE
PHILADELPHIA, PA 19106

ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA

DWG 108




- 1: Column 3 flutes 14-18 (drum 3). An example of (a) stone redressing (b) differential erosion, and (c) incipient spalling.
- 2: Column 3 flutes 17-18 (drum 2). An example of (a) contour scaling, (b) differential erosion, and (c) significant dimensional loss.
- 3: Column 1 flutes 16-21. An example of (a) a mineral inclusion, (b) stone redressing, and (c) dimensional loss.





CONDITIONS LEGEND

- | | | |
|---|--|--|
| <ul style="list-style-type: none"> Open Joint Deteriorated Joint Mortar Major Crack Moderate Crack Network Cracking Friability/Flaking Contour Scaling Differential Erosion Incipient Spalling Dimensional Loss | <ul style="list-style-type: none"> Filled Crack Less Than 1/4 Filled Crack Greater Than 1/4 Repointing Chemical Bird Repellent Treatment Coating Stone Redressing Stone Dutchman Stone Replacement Composite Repair Sealant Foliation Orientation | <ul style="list-style-type: none"> Intrinsic Metallic Staining Extrinsic Metallic Staining Non-Intrinsic Staining Microflora Efflorescence Encrustation Deformation/Displacement Mineral Inclusion Defective Mechanical System Railing Remnant |
|---|--|--|



Column Fluting Plan



SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA

CHARLES TONETTI, INDEPENDENCE NATIONAL HISTORICAL PARK
FRANK MATERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN





SPONSORED BY: PARK SERVICE
CAM OFFICE
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106

CONDITION ASSESSMENT:
JOHN GLAVAN
LAUREN HEGERTY
JOHN HOWARD
KERRY JOHNSTON
SOPHIA MIDDLEBROOK

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA




DWG 109



1: Column 8 flutes 8-13. An example of (a) dimensional loss and (b) stone redressing.



2: Column 8 flutes 12-15. An example of (a) intrinsic metallic staining, (b) sealant, (c) stone redressing, and (d) dimensional loss.

3: Column 5 flutes 17-20. Various conditions including (a) contour scaling, (b) sealant, and (c) dimensional loss.




CONDITIONS LEGEND

- | | | |
|--|--|---|
| <ul style="list-style-type: none"> Open Joint Deteriorated Joint Mortar Major Crack Moderate Crack Network Cracking Friability/F laking Contour Scaling Differential Erosion Incipient Spalling Dimensional Loss | <ul style="list-style-type: none"> Filled Crack Less Than 1/4" Filled Crack Greater Than 1/4" Repointing Chemical Bird Repellent Treatment Coating Stone Redressing Stone Dutchman Stone Replacement Composite Repair Sealant Foliage Orientation | <ul style="list-style-type: none"> Intrinsic Metallic Staining Extrinsic Metallic Staining Non-Intrinsic Staining Microflora Efflorescence Encrustation Deformation / Displacement Mineral Inclusion Defective Mechanical Systems Railing Remnant |
|--|--|---|



Column Fluting Plan



SOUTH PORTICO
COLUMNS 5 - 8

SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA

SPONSORED BY: PARK SERVICE
CAM OFFICE
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106

CONDITION ASSESSMENT:
JOHN GLAVAN
LAUREN HEGERTY
JOHN HOWARD


PROJECT SUPERVISORS:
FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER:
JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA



DWG 110

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

FLOOR AND STAIR TREADS




STAIR RISERS



CONDITIONS LEGEND

- | | | |
|---------------------------------|--------------------------------------|-----------------------------------|
| Open Joint | Filled Crack Less Than 1/4" | Intrinsic Metallic Staining |
| Deteriorated Joint Mortar | Filled Crack Greater Than 1/4" | Extrinsic Metallic Staining |
| Major Crack | Repointing | Non- Intrinsic Staining |
| Moderate Crack | Chemical Bird Repellent | Microflora |
| Network Cracking | Treatment Coating | Efflorescence |
| Friability/F laking | Stone Redressing | Encrustation |
| Contour Scaling | Stone Dutchman | Deformation/Displacement |
| Differential Erosion | Stone Replacement | Mineral Inclusion |
| Incipient Spalling | Composite Repair | Defective Mechanical System |
| Dimensional Loss | Sealant | Railing Remnant |
| | Foliation Orientation | |



**SECOND BANK OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA**

PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN

**SOUTH PORTICO
FLOOR AND STAIRS**


CONDITION ASSESSMENT:
JOHN GLAVAN
LAUREN HEGERTY
JOHN HOWARD

SPONSORED BY: PARK SERVICE
CAMDEN OFFICE
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA 19106


DWG 111

SITE RECORDING: SUMMER 2003
DATA INPUT: FALL 2003

SOFFIT




REFLECTED CEILING




CONDITIONS LEGEND

- | | | |
|--|--|--|
| <ul style="list-style-type: none"> Open Joint Deteriorate Joint Mortar Major Crack Moderate Crack Network Cracking Friability/Flaking Contour Scaling Differential Erosion Incipient Spalling Dimensional Loss | <ul style="list-style-type: none"> Filled Crack Less Than 1/4" Filled Crack Greater Than 1/4" Repointing Chemical Bird Repellent Treatment Coating Stone Redressing Stone Dutchman Stone Replacement Composite Repair Sealant Foliage Orientation | <ul style="list-style-type: none"> Intrinsic Metallic Staining Extrinsic Metallic Staining Non-Intrinsic Staining Microflora Efflorescence Encrustation Deformation/Displacement Mineral Inclusion Defective Mechanical System Railing remnant |
|--|--|--|



**SOUTH PORTICO
CORNICE SOFFIT AND CEILING**


<p>SECOND BANK OF THE UNITED STATES INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA</p> <p>PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>	<p>SPONSORED BY: PARK SERVICE CAM OFFICE INDEPENDENCE NATIONAL HISTORICAL PARK PHILADELPHIA, PA 19106</p> <p>CONDITION ASSESSMENT: JOHN GLAVAN LAUREN HEGERTY JOHN HOWARD</p> <p>KERRY JOHNSTON SOPHIA MIDDLEBROOK</p>
<p>ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA</p>	
<p>SITE RECORDING: SUMMER 2003 DATA INPUT: FALL 2003</p>	
<p>DWG 112</p>	




Orientation of Foliation Planes

- No Data
- Face Oriented
- Edge Oriented: Horizontal
- Edge Oriented: Diagonal
- Edge Oriented: Diagonal
- Edge Oriented: Vertical

0 5 10 20 Feet




<p>SECOND BANK OF THE UNITED STATES INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA</p>		<p>SOUTH PORTICO ORIENTATION OF FOLIATION PLANES</p>	
<p>PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>	<p>SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE CAMDEN OFFICE INDEPENDENCE NATIONAL HISTORICAL PARK PHILADELPHIA, PA 19106</p>	<p>CONDITION ASSESSMENT: JOHN GLAVAN LAUREN HEGERTY JOHN HOWARD</p>	<p>KERRY JOHNSTON SOPHIA MIDDLEBROOK</p>
<p>PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN</p>	<p>ARCHITECTURAL CONSERVATION LABORATORY AND RESEARCH CENTER THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA</p>		<p>SITE RECORDING: SUMMER 2003 DATA INPUT: FALL 2003</p>
			<p>DWG 113</p>



Orientation of Foliation Planes

- No Data
- Face Oriented
- Edge Oriented: Horizontal
- ↗ Edge Oriented: Diagonal
- ↘ Edge Oriented: Diagonal
- ↑ Edge Oriented: Vertical



SECOND BANK OF THE UNITED STATES INDEPENDENCE NATIONAL HISTORICAL PARK, PHILADELPHIA, PA		EAST ELEVATION FOLIATION ORIENTATION
PROJECT SUPERVISOR: FRANK MATTERO, ARCHITECTURAL CONSERVATION LABORATORY, UPENN	SPONSORED BY: NATIONAL HISTORICAL PARK SERVICE CAMDEN OFFICE INDEPENDENCE NATIONAL HISTORICAL PARK PHILADELPHIA, PA 19106	CONDITION ASSESSMENT: JOHN GLAVAN LAUREN HEGERTY JOHN HOWARD KERRY JOHNSTON SOPHIA MIDDLEBROOK
PROJECT MANAGER: JOHN HINCHMAN, ARCHITECTURAL CONSERVATION LABORATORY, UPENN		SITE RECORDING: SUMMER 2003 DATA INPUT: FALL 2003
THE GRADUATE PROGRAM IN HISTORIC PRESERVATION THE SCHOOL OF DESIGN UNIVERSITY OF PENNSYLVANIA		DWG 114



1 2 3 4 5 6 7 8

A


B

C

D

E

F



REQUIRES INTERVENTION

- Major Cracks
- Incipient Spall - 1/2" deep
- Incipient Spall + 1/2" deep
- Dimensional Loss
- Deformation/Displacement
- Open Joints (dashed)
- Defective Building Systems

REQUIRES MONITORING

- Orientation of foliation
- Mineral Inclusions
- Moderate Cracks
- Active Friability or Flaking
- Surface Erosion
- Contour Scaling
- Deteriorating Mortar (dashed)
- Efflorescence
- Encrustation
- Composite Patches
- Filled Cracks - 1/4"
- Filled Cracks + 1/4"
- Treatment Coatings
- Historic Stone Loss

OBSERVATION - ROUTINE MAINTENANCE

- Map Cracking Zone
- Texture (V) or (H)
- Tooling Marks (T)
- Inappropriate Sealants
- Metallic Staining
- Microflora
- Chemical Bird Treatment
- Animal-Insect Activity
- Brown Streaking
- Repointing Repairs
- Stone Dutchman
- Historic Stone Replacement

SECOND BANK

OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:


PROJECT COORDINATION:

PROJECT MANAGER:

PROJECT CONSULTANTS

TECHNICAL SUPPORT:

DOCUMENTATION TEAM:



NORTH PORTICO COLUMNS AND BACKWALL

ISSUE DATE:
REVISION: DESCRIPTION DATE

CA-1.01

SCALE: 1/4 inch = 1 foot

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BINDERS OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT NHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE: PLOTTED:
CONDITIONS ASSESSMENT SURVEY:






1 2 3 4 5 6 7 8

A
B
C
D
E
F

- | | | |
|------------------------------|-------------------------------|--|
| REQUIRES INTERVENTION | REQUIRES MONITORING | ROUTINE MAINTENANCE - OBSERVATION |
| Major Cracks | Orientation of foliation | Map Cracking Zone |
| Incipient Spall - 1/2" deep | Mineral Inclusions | Texture (V) or (H) |
| Incipient Spall + 1/2" deep | Moderate Cracks | Tooling Marks (T) |
| Dimensional Loss | Active Friability or Flaking | Inappropriate Sealants |
| Deformation/Displacement | Surface Erosion | Metallic Staining |
| Open Joints (dashed) | Contour Scaling | Microflora |
| Defective Building Systems | Deteriorating Mortar (dashed) | Chemical Bird Treatment |
| | Efflorescence | Animal-Insect Activity |
| | Encrustation | Brown Streaking |
| | Composite Patches | Repointing Repairs |
| | Filled Cracks - 1/4" | Stone Dutchman |
| | Filled Cracks + 1/4" | Historic Stone Replacement |
| | Treatment Coatings | |
| | Historic Stone Loss | |
- Stone repair with epoxy and mortared edges
 Indicates the foliation direction could not be determined.



C1 NORTH PORTICO PEDIMENT - East Half
SCALE 1/4" = 1' 0"

SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106

ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
DORIS FANELLI


PROJECT COORDINATION:
BELL BROOKOVER
TODD HART

PROJECT MANAGER:
GUY MUNSCH

PROJECT CONSULTANTS
FRANK MATERO

TECHNICAL SUPPORT:
DPK&A
CYRA TECHNOLOGIES

DOCUMENTATION TEAM:
LORI AUMENT
ELSA BOURGUIGNON
CATHERINE DEWEY
CLAUDIA HARBERT
DIANE JACKIER
MARNE NEWMAN



NORTH PORTICO PEDIMENT

ISSUE DATE: AUGUST 12, 1999

REVISION:	DESCRIPTION	DATE

CA-1.02-a



NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, SERIES OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT INHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE ONE PLOTTED: 08/20/99 - GRM
CONDITIONS ASSESSMENT SURVEY: N-W ELEVATIONS





1 2 3 4 5 6 7 8

A

B


C

D

E

F

- | | | |
|------------------------------|-------------------------------|--|
| REQUIRES INTERVENTION | REQUIRES MONITORING | ROUTINE MAINTENANCE - OBSERVATION |
| Major Cracks | Orientation of foliation | Map Cracking Zone |
| Incipient Spall - 1/2" deep | Mineral Inclusions | Texture (V) or (H) |
| Incipient Spall + 1/2" deep | Moderate Cracks | Tooling Marks (T) |
| Dimensional Loss | Active Friability or Flaking | Inappropriate Sealants |
| Deformation/Displacement | Surface Erosion | Metallic Staining |
| Open Joints (dashed) | Contour Scaling | Microflora |
| Defective Building Systems | Deteriorating Mortar (dashed) | Chemical Bird Treatment |
| | Efflorescence | Animal-Insect Activity |
| | Encrustation | Brown Streaking |
| | Composite Patches | Repointing Repairs |
| | Filled Cracks - 1/4" | Stone Dutchman |
| | Filled Cracks + 1/4" | Historic Stone Replacement |
| | Treatment Coatings | |
| | Historic Stone Loss | |
- Stone repair with epoxy and mortared edges
 Indicates the foliation direction could not be determined.



1. Entire raking cornice has metallic staining from the roof

C1 NORTH PORTICO PEDIMENT - West Half
SCALE 1/4" = 1' 0"

SECOND BANK
OF THE UNITED STATES

INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106

ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
DORIS FANELLI


PROJECT COORDINATION:
BELL BROOKOVER
TODD HART

PROJECT MANAGER:
GUY MUNSCH

PROJECT CONSULTANTS
FRANK MATERO

TECHNICAL SUPPORT:
DPK&A
CYRA TECHNOLOGIES

DOCUMENTATION TEAM:
LORI AUMENT
ELSA BOURGUIGNON
CATHERINE DEWEY
CLAUDIA HARBERT
DIANE JACKIER
MARNE NEWMAN



NORTH PORTICO PEDIMENT

ISSUE DATE: AUGUST 12, 1999

REVISION:	DESCRIPTION	DATE

CA-1.02-b



NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, SERIES OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT INHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE ONE PLOTTED: 08/20/99 - GRM
CONDITIONS ASSESSMENT SURVEY: N-II ELEVATIONS





1 2 3 4 5 6 7 8

A


B

C

D

E

F



REQUIRES INTERVENTION

- Major Cracks
- Incipient Spall - 1/2" deep
- Incipient Spall + 1/2" deep
- Dimensional Loss
- Deformation/Displacement
- Open Joints (dashed)
- Defective Building Systems

REQUIRES MONITORING

- Orientation of foliation
- Mineral Inclusions
- Moderate Cracks
- Active Friability or Flaking
- Surface Erosion
- Contour Scaling
- Deteriorating Mortar (dashed)
- Efflorescence
- Encrustation
- Composite Patches
- Filled Cracks - 1/4"
- Filled Cracks + 1/4"
- Treatment Coatings
- Historic Stone Loss

OBSERVATION - ROUTINE MAINTENANCE

- Map Cracking Zone
- Texture (V) or (H)
- Tooling Marks (T)
- Inappropriate Sealants
- Metallic Staining
- Microflora
- Chemical Bird Treatment
- Animal-Insect Activity
- Brown Streaking
- Repointing Repairs
- Stone Dutchman
- Historic Stone Replacement

SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
DORIS FANELLI


PROJECT COORDINATION:
BILL BROOKOVER
TODD HART

PROJECT MANAGER:
GUY MUNSCH

PROJECT CONSULTANTS
FRANK MATERO

TECHNICAL SUPPORT:
DPK&A
CYRA TECHNOLOGIES

DOCUMENTATION TEAM:
LORI AUMENT
ELSA BOURGUIGNON
CATHERINE DEWEY
CLAUDIA HARBERT
DIANE JACKIER
MARNIE NEWMAN



**NORTH PORTICO
FACADE BACK WALL**

ISSUE DATE: AUGUST 12, 1999

REVISION:	DESCRIPTION	DATE

CA-1.03

SCALE 1/4" = 1' 0"

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, SERIES OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT ANHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA.

PHASE ONE PLOTTED: 08/20/99 - GRM
CONDITIONS ASSESSMENT SURVEY: N-W ELEVATIONS





1 2 3 4 5 6 7 8

Easternmost Column Number One

Column Number Two





Column Number Three

Column Number Four

A

B

C



- REQUIRES INTERVENTION**
- Major Cracks
 - Incipient Spall - 1/2" deep
 - Incipient Spall + 1/2" deep
 - Dimensional Loss
 - Deformation/Displacement
 - Open Joints (dashed)
 - Defective Building Systems
- REQUIRES MONITORING**
- Orientation of foliation
 - Mineral Inclusions
 - Moderate Cracks
 - Active Friability or Flaking
 - Surface Erosion
 - Contour Scaling
 - Deteriorating Mortar (dashed)
 - Efflorescence
 - Encrustation
 - Composite Patches
 - Filled Cracks - 1/4"
 - Filled Cracks + 1/4"
 - Treatment Coatings
 - Historic Stone Loss

Column Number Five

Column Number Six





Column Number Seven

Westernmost Column Number Eight


D

E

F



- OBSERVATION - ROUTINE MAINTENANCE**
- Map Cracking Zone
 - Texture (V) or (H)
 - Tooling Marks (T)
 - Inappropriate Sealants
 - Metallic Staining
 - Microflora
 - Chemical Bird Treatment
 - Animal-Insect Activity
 - Brown Streaking
 - Repointing Repairs
 - Stone Dutchman
 - Historic Stone Replacement



SECOND BANK


OF THE UNITED STATES

INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106

ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
PROJECT COORDINATION:
PROJECT MANAGER:
PROJECT CONSULTANTS
TECHNICAL SUPPORT:
DOCUMENTATION TEAM:



NORTH PORTICO COLUMN ROLL-OUT

ISSUE DATE:	REVISION:	DESCRIPTION:	DATE:

CA-1.04

SCALE: 1/4 inch = 1 foot

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BUNDLES OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT INHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE TWO PLOTTED:
CONDITIONS ASSESSMENT SURVEY





1 2 3 4 5 6 7 8

A

REQUIRES INTERVENTION

- Major Cracks
- Incipient Spall - 1/2" deep
- Incipient Spall + 1/2" deep
- Dimensional Loss
- Deformation/Displacement
- Open Joints (dashed)
- Defective Building Systems

B

REQUIRES MONITORING

- Orientation of foliation
- Mineral Inclusions
- Moderate Cracks
- Active Friability or Flaking
- Surface Erosion
- Contour Scaling
- Deteriorating Mortar (dashed)

C

- Efflorescence
- Encrustation
- Composite Patches
- Filled Cracks - 1/4"
- Filled Cracks + 1/4"
- Treatment Coatings
- Historic Stone Loss


D

OBSERVATION - ROUTINE MAINTENANCE

- Map Cracking Zone
- Texture (V) or (H)
- Tooling Marks (T)
- Inappropriate Sealants
- Metallic Staining
- Microflora
- Chemical Bird Treatment
- Animal-Insect Activity
- Brown Streaking
- Repointing Repairs
- Stone Dutchman
- Historic Stone Replacement

E


F



SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
PROJECT COORDINATION:
PROJECT MANAGER:
PROJECT CONSULTANTS
TECHNICAL SUPPORT:
DOCUMENTATION TEAM:



WEST ELEVATION
SOUTH HALF

ISSUE DATE:	REVISION:	DESCRIPTION:	DATE:

CA-1.05

SCALE: 1/4 inch = 1 foot


NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BINDERS OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT NHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE: PLOTTED:
CONDITIONS ASSESSMENT SURVEY:





1 2 3 4 5 6 7 8




- REQUIRES INTERVENTION**
- Major Cracks
 - Incipient Spall - 1/2" deep
 - Incipient Spall + 1/2" deep
 - Dimensional Loss
 - Deformation/Displacement
 - Open Joints (dashed)
 - Defective Building Systems
- REQUIRES MONITORING**
- Orientation of foliation
 - Mineral Inclusions
 - Moderate Cracks
 - Active Friability or Flaking
 - Surface Erosion
 - Contour Scaling
 - Deteriorating Mortar (dashed)
 - Efflorescence
 - Encrustation
 - Composite Patches
 - Filled Cracks - 1/4"
 - Filled Cracks + 1/4"
 - Treatment Coatings
 - Historic Stone Loss
- OBSERVATION - ROUTINE MAINTENANCE**
- Map Cracking Zone
 - Texture (V) or (H)
 - Tooling Marks (T)
 - Inappropriate Sealants
 - Metallic Staining
 - Microflora
 - Chemical Bird Treatment
 - Animal-Insect Activity
 - Brown Streaking
 - Repointing Repairs
 - Stone Dutchman
 - Historic Stone Replacement

SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
PROJECT COORDINATION:
PROJECT MANAGER:
PROJECT CONSULTANTS
TECHNICAL SUPPORT:
DOCUMENTATION TEAM:



WEST ELEVATION
SOUTH HALF

REVISION	DESCRIPTION	DATE

CA-1.06

SCALE: 1/4 inch = 1 foot

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BINDERS OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT NHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE: 100 | PLOTTED: 10/1/2014 10:00 AM
CONDITIONS ASSESSMENT SURVEY





1 2 3 4 5 6 7 8

A


B

C

D



E

F



1. Entire raking cornice has metallic staining from the roof


- REQUIRES INTERVENTION**
- Major Cracks
 - Incipient Spall - 1/2" deep
 - Incipient Spall + 1/2" deep
 - Dimensional Loss
 - Deformation/Displacement
 - Open Joints (dashed)
 - Defective Building Systems
- REQUIRES MONITORING**
- Orientation of foliation
 - Mineral Inclusions
 - Moderate Cracks
 - Active Friability or Flaking
 - Surface Erosion
 - Contour Scaling
 - Deteriorating Mortar (dashed)
 - Efflorescence
 - Encrustation
 - Composite Patches
 - Filled Cracks - 1/4"
 - Filled Cracks + 1/4"
 - Treatment Coatings
 - Historic Stone Loss
- OBSERVATION - ROUTINE MAINTENANCE**
- Map Cracking Zone
 - Texture (V) or (H)
 - Tooling Marks (T)
 - Inappropriate Sealants
 - Metallic Staining
 - Microflora
 - Chemical Bird Treatment
 - Animal-Insect Activity
 - Brown Streaking
 - Repointing Repairs
 - Stone Dutchman
 - Historic Stone Replacement



SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:
PROJECT COORDINATION:
PROJECT MANAGER:
PROJECT CONSULTANTS
TECHNICAL SUPPORT:
DOCUMENTATION TEAM:



**NORTH PORTICO
PEDIMENT AND UNDERSIDE OF
MUTULES**

REVISION:	DESCRIPTION	DATE


CA-1.07

SCALE: 1/4 inch = 1 foot

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BUNDLES OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT ANHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE: PLOTTED:
CONDITIONS ASSESSMENT SURVEY





REQUIRES INTERVENTION

- Major Cracks
- Incipient Spall - 1/2" deep
- Incipient Spall + 1/2" deep
- Dimensional Loss
- Deformation/Displacement
- Open Joints (dashed)
- Defective Building Systems

REQUIRES MONITORING

- Orientation of foliation
- Mineral Inclusions
- Moderate Cracks
- Active Friability or Flaking
- Surface Erosion
- Contour Scaling
- Deteriorating Mortar (dashed)
- Efflorescence
- Encrustation
- Composite Patches
- Filled Cracks - 1/4"
- Filled Cracks + 1/4"
- Treatment Coatings
- Historic Stone Loss

OBSERVATION - ROUTINE MAINTENANCE

- Map Cracking Zone
- Texture (V) or (H)
- Tooling Marks (T)
- Inappropriate Sealants
- Metallic Staining
- Microflora
- Chemical Bird Treatment
- Animal-Insect Activity
- Brown Streaking
- Repointing Repairs
- Stone Dutchman
- Historic Stone Replacement

SECOND BANK
OF THE UNITED STATES
INDEPENDENCE NATIONAL HISTORICAL PARK
PHILADELPHIA, PA

SPONSORED BY:
NATIONAL PARK SERVICE
CRM OFFICE
INDEPENDENCE NATIONAL
HISTORICAL PARK
PHILADELPHIA, PA 19106
ARCHITECTURAL CONSERVATION
LABORATORY
UNIVERSITY OF PENNSYLVANIA
PHILADELPHIA, PA 19104

PROJECT DIRECTOR:


PROJECT COORDINATION:

PROJECT MANAGER:

PROJECT CONSULTANTS

TECHNICAL SUPPORT:

DOCUMENTATION TEAM:



NORTH PORTICO
FLOOR AND STAIRS
AND INTERIOR RETURN WALLS

ISSUE DATE:

REVISION: DESCRIPTION DATE

CA-1.08

SCALE: 1/4 inch = 1 foot

NOTE: ASSOCIATED DATABASE FILE BY STONE NUMBER, BINDERS OF PHOTOGRAPHS AND ARCHIVAL RESEARCH, AND MATERIALS TESTING DATA ARE STORED AT INHP ARCHIVES AND THE ACL LABORATORY AT THE UNIVERSITY OF PENNSYLVANIA

PHASE: **1** PLOTTED: **1**
CONDITIONS ASSESSMENT SURVEY



8.0 Material Analysis

Selective analysis was conducted on the Pennsylvania marble from the north portico in 1999. (see Section 8.2) Characterization included confirmation of the mineral content of the marble inclusions, black gypsum crusts, and the identification of brown streaking apparent on the façade that was believed to be residues of the earlier 1964 water-proofing.

Previous testing of Pennsylvania marble has been performed at different times for each of the three major Pennsylvania marble buildings in the park. The stone of the Second Bank was studied by Jocelyn Kimmel as part of a graduate thesis in 1996 and for the First Bank by Guy Munsch as part of a graduate thesis in 1998. Additionally, stone at the Merchant's Exchange was examined as part of a multi-year Conservation Strategy⁵⁰. Further analysis and testing will proceed upon completion of the exterior conditions survey. Testing as required to evaluate specific treatment and repair strategies will also need to be incorporated into the future phases of the project.

Scanning electron micrographs (SEM) of collected samples from protected areas show a blistered coating on the surface of the marble. (Fig. 13) To confirm the visual observations, an X-ray (EDS) analysis was performed. A central target inside the opening of the coating was selected and an elemental spectra was recorded. A second target over the coated surface was then used for a second reading.





Figure 13: SEMicrograph of north portico sample (Magnification 150x).

⁵⁰ Brookover, McGee, Mossotti, Dolske and Sherwood, 1992


The spectra below on the left shows the marble surface without the coating. It exhibits a high calcite (Ca) peak with minimal readings for silicon (Si) and iron (Fe). The spectra below on the right, taken from the coated area, still has a high peak for the dominant mineral of the marble, calcite, but there is a substantial increase in the silicon and the iron peaks. The silicon confirms the presence of the 1964 silicone-based waterproofing polymer coating (Hydrozo-Clearstone). The presence of iron can be attributed to intrinsic accessory minerals present in the stone that would have naturally weathered off of the surface but is now held just below the surface of the film, contributing to the orange-brown staining on the surface of the marble.

Several samples were taken from the north façade of the Second Bank in 1999. Following are short summaries of a range of samples tested using X-ray diffraction analysis to confirm physical compositions of some of the more prominent inclusions, a white powdering on the surface, and soiling identified as gypsum and particulate sulfation crusts.

Analyses were conducted on stone samples using an X-Ray Diffraction Rigaku Diffractometer at the Laboratory for Research on the Structure of Matter (LRSM) at the University of Pennsylvania. The instrument was set at kilovolts and milliamps. The scans were run between 5 and 65 degrees 2 θ , at 2 degrees per minute. All of the samples were reduced into powder with a mortar and pestle. A glass slide was prepared by covering it with a thin layer of Vaseline and spreading the powder over it.



XRD, marble surface without coating



XRD, marble surface with coating

8.1 Analysis Summary

Samples taken from the north portico of the Second Bank of the United States, Philadelphia, PA.

8.1.1 Marble Dust

From an unknown area of the North façade (ground collection) XRD, Files Z12228.raw and Z12228.pks

Best match for marble dust is JCPDS spectrum 72 1651, calcium carbonate (calcite). The Pennsylvania Blue marble is mainly composed of calcite (CaCO_3). Secondary minerals from the marble did not display any prominent peaks.

8.1.2 Mineral Inclusion 1 (MI.1)

XRD, Files Z12229.raw and Z12229.pks

Best match for mineral inclusion 1 is JCPDS spectrum 83 0577, calcium carbonate. A secondary search was carried out on the spectrum of mineral inclusion 1 minus 82 0577. Two good matches of the resulting spectrum were JCPDS spectrum 06 0263, potassium aluminum silicate hydroxide (muscovite 2M#1) and JCPDS spectrum 40 0020, potassium magnesium aluminum silicate hydroxide. It is expected that calcite is the dominant mineral since almost all samples were sampled by scraping the stones, and are mixed with marble dust. The mineral inclusion is probably a type of muscovite.

8.1.3 Mineral Inclusion 2 (MI.2)

XRD, Files Z1 2230.raw and Z1 2230.pks

Best match for mineral inclusion 2 is JCPDS spectrum 06 0263, potassium aluminum silicate hydroxide (muscovite 2M#1). Second best match is JCPDS spectrum 76 0929, potassium aluminum oxide silicate hydroxide (muscovite 2M1). Calcite does not appear as a dominant mineral in this sample. It is probably a relatively pure sample of the inclusion, minimally contaminated by the marble dust. Mineral inclusion 2 is similar to mineral inclusion 1. It belongs to the muscovite mineral family.

8.1.4 Mineral Inclusion 3 (MI.3)

XRD, Files Z12231.raw and Z12231.pks

Best match for mineral inclusion 3 is JCPDS spectrum 77 2255, potassium aluminum silicate hydroxide (muscovite). Second best match is JCPDS spectrum 76-0929, potassium aluminum oxide silicate hydroxide (muscovite 2M1). JCPDS spectrum 40 0020, potassium magnesium aluminum silicate hydroxide, second best match for mineral inclusion 1, is the sixth best match for mineral inclusion 3. JCPDS spectrum 6 0263, potassium aluminum silicate hydroxide (muscovite 2M#1), best match for mineral inclusion 2, is the seventh best match of mineral inclusion 3.

Mineral inclusion 3 is similar to mineral inclusions 1 & 2. It belongs to the muscovite mineral family.

8.1.5 Mineral Inclusion 3 (MI.4)

XRD, Files Z12232.raw and Z12232.pks

Best match for mineral inclusion 4 is JCPDS spectrum 5 0586, calcium carbonate (calcite). A secondary search was carried out on the spectrum of mineral inclusion 4 minus 5 0586. The best match of the resulting spectrum was JCPDS spectrum 82 1572, silicon oxide. The second best match is JCPDS spectrum 76 0668, potassium aluminum silicate hydroxide (muscovite 2M1). A tertiary search was carried out on the spectrum of mineral inclusion 4 minus calcite (5-0586) minus muscovite (76 0668). The best match of the resulting spectrum was JCPDS spectrum 42 1340, iron sulfide (pyrite). Mineral inclusion 4 has a different color and appearance than mineral inclusions 1, 2 and 3. The first three were gray and very layered, almost fibrous. Number 4 was red brownish and of a smaller quantity. The best match of mineral inclusion 4 minus calcite is silicon oxide. (Note: As later testing confirmed evidence of a silicone based coating, the results of this test would seem to reflect the presence of the coating material on the marble sample.)

8.1.6 White Deposit 1 (W1)

XRD, Files Z12233.raw and Z12233.pks

Best match for the white deposit is JCPDS spectrum 70 0984, calcium sulfate hydrate (gypsum). The white deposit is present in areas which may not receive rain water washing through direct exposure or run off.

8.1.7 White Deposit 3 (W3)

XRD, Files Z12244.raw and Z12244.pks

Best match for the white deposit is JCPIDS spectrum 72 0596, calcium sulfate hydrate (gypsum).

8.1.8 Gypsum Crust 1 (G1)

XRD, Files Z12246.raw and Z12246.pks

Best match for gypsum crust 1 is JCPIDS spectrum 72 1650, calcium carbonate (calcite). A secondary search was carried out on the spectrum minus 72 1650. The best match of the resulting spectrum is JCPDS 6 0046, calcium sulfate hydrate (gypsum).

8.1.9 Gypsum Crust 2 (G2)

XRD, Files Z12247.raw and Z12247.pks

The best match for this sample is JCPDS spectrum 70 0095, calcium carbonate (calcite). A secondary search was carried out on the spectrum minus 70 0095. None of the matches


proposed by the database for the secondary search was appropriate for this type of sample, gypsum did not appear in the spectrum. The sample appears to be a soiled sample of friable marble, but is not in a deterioration state that has produced a true gypsum crust. The analysis underlines the difficulties in distinguishing a real gypsum crust deterioration pattern from a surface soiling of the marble.

8.1.10 Gypsum Crust 3 (G3)

XRD, Files Z12248.raw and Z12248.pks

The best match for this sample is JCPIDS spectrum 72 1652, calcium carbonate (calcite). A secondary search was carried out on the spectrum minus 72 1652. The best match of the resulting spectrum is JCPDS spectrum 6 0263, potassium aluminum silicate hydroxide (muscovite 2M1). A tertiary search was carried out on the sample, the third best match is 78 1253, silicon oxide (quartz alpha). The sixth best match is 36 0432, calcium sulfate hydrate (gypsum). The sample contains the dominant mineral from the marble, calcite, and from an apparent inclusion, muscovite, there are traces of the silicone treatment coating and of a mild gypsum crust.

8.2 Sample Locations



Locations and identification numbers of samples taken from the north façade in 1999.

9.0 Recommendations for Future Phases

- Emergency Interventions: Correct all defective building systems, re-point all open joints with a lime-based mortar, make temporary or limited experimental repairs to all spalls and areas of dimensional loss greater than 3" in diameter or as required.
- Use close range photogrammetry or laser scanning to monitor selected areas of stone alterations and loss and calculate rate of loss in the most vulnerable areas. Monitor cracks at key conditions to determine movement.
- Begin test pinning, patching and grouting methods to stabilize areas of deteriorated stone. Install a range of test panels to assess the performance of consolidants and water repellents as a follow up to the 1995 laboratory testing.
- Create a summary of all previous testing programs of Pennsylvania Marble done in conjunction with previous research projects at INHP, and determine the successes, the failures and the unknowns. Recommend which testing values can be accepted as a normal range for the performance of Pennsylvania marble and outline any new testing programs that must be completed in future phases.
- Explore opportunities for improving survey methodology and the potential for additional decay mapping with close-range stereophotogrammetry and laser scanning to determine deterioration patterns and rates.
- Pursue additional research and funding partnerships where appropriate. Develop a comprehensive plan for the exterior conservation and treatment of the Second Bank, the First Bank and the Merchant's Exchange as needed. Explore this plan as an internal or external project both in terms of funding and staffing. Consider bringing the three projects together into one major initiative for NPS-INHP.
- Convert 1999 drawings into 2003 format using ArcView.
- Conduct a full analysis of the building using the analytical capabilities of GIS. Analysis should begin with the portico columns, as they exhibit the most complex deterioration patterns.

10.0 Bibliography

10.1 Published Sources

- 1) Accardo, G., R. Cassano, P. Rossi-Doria, P. Sammuri, and M. Tabasso. "Screening of Products and Methods for the Consolidation of Marble." *The Conservation of Stone 11. Preprints of the Contributions to the International Symposium, Bologna. 27-30 October 1981, Part B, 721-735.* Edited by Raffaella Rossi-Manaresi. Bologna: Centro per la Conservazione Delle Sculture All'Aperto, 1981.
- 2) Alberti, S. A. et al. "CastelManiace, Syracuse (Sicily): the deterioration of the marble of the monumental portal and window." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone.* New York: Elsevier, 1989, v. 2, pp. 649-660.
- 3) Amoroso, G.G., and V. Fassina. *Stone Decay and Conservation.* Amsterdam, Elsevier, 1983. *Analectic Magazine* 13 no. 3 (March, 1819).
- 4) Ashurst, John and Francis G. Dimes. *Conservation of Decorative and Building Stone. Volumes One and Two.* Boston: Butterworths, 1990.
- 5) Ashurst, John and Francis G. Dimes. *Stone in Building.* Architectural Press Ltd: London, 1977.
- 6) Ashurst, John, and Nicola Ashurst. *Practical Building Conservation. Volume One: Stone Masonry.* New York: Halsted Press, 1988.
- 7) Ashurst, Nicola. *Cleaning Historic Buildings, Vol. 1,* London: Donhead Publishing Limited.1994. 28-36.
- 8) Ausset, P. et al. "Early mechanisms of development of sulphated crusts on carbonate stone." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone.* New York: Elsevier, 1989, v. 1, pp.329-338.
- 9) Baer, Norbert S. And Manfred J.D. Low. "Advances in Scientific Instrumentation for Conservation: An Overview." *Science and Technology in the Service of Conservation. Preprints of the Contributions to the Washington Congress, September 3-9, 1982.* International Institute for Conservation of Historic and Artistic Works: London. Pgs. 1-4.
- 10) Beckman, Mike. "Polymers for Stone Fabrication and Repair." *Stone World.* June 1997. Pgs.95-97.
- 11) Bede, E. A. "Characterization of surface morphology of carbonate stone and its effect on surface uptake of SO₂." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone.* New York: Elsevier, 1989, v. 1, pp. 303312.
- 12) Beloyannis, Nicholas, and Dascalakis, Stylianos. "Marine deterioration of marbles from the Cyclades; the case of the marble statues in Delos and Naxos." *Proceedings of the 1st International Symposium on the Conservation of Monuments in the Mediterranean Basin.* Bari, 1989, pp. 189-193.
- 13) Biscontin, G., and G. Riva. "Study About Water Vapour Permeability in Stone Materials After Protective Treatment," in *Conservation of Stone II,* 689-697.

- 14) Blatt, Harvey, and Robert J. Tracy. *Petrology: Igneous, Sedimentary and Metamorphic*. Second edition. New York: W.H. Freeman and Company, 1996.
- 15) Bortz, S., et al. "Accelerated Weathering in Building Stone." In *International Journal of Rock Mechanics and Mining Sciences* 30 no. 7, 1993: 1559-1562.
- 16) Bortz, S.A., Erlin, B., and Monk, C.B., Jr. "Some field problems with thin veneer building stones." *New stone technology, design, and construction for exterior wall systems*, ASTM STP 996, B. Donaldson, ed. Philadelphia: ASTM, 1988. pp. 11-31.
- 17) Brennan, Patrick, and Carol Fedor. "Sunlight, UV and Accelerated Weathering." Report presented at the Society of Plastic Engineers, Automotive RETEC. November 1987,
- 18) Brookover, William D., Elaine S. McGee, Victor G. Mossotti, Donald A. Dolske and Susan I. Sherwood. *Philadelphia Merchants' Exchange Conservation Strategy*. National Park Service, Preservation Assistance Division: Washington, DC, 1992.
- 19) Calla, A., L. Lazzarini, E. Pellegrino, M. Preite Martinez, and B. Turi. "The Identification of the Marble of the Great Apsidal Window of Bari Cathedral: A Mineralogical, Petrographic and Isotopic Study." *Science and Technology for Cultural Heritage*. Giardini Editorie Stampod: Pisa, 1992, pgs. 191-201.
- 20) Camuffo, D. "Deterioration Processes of Historical Monuments." *Proceedings of the International Conference on Acidification and its Policy Implications*. United Nations Economic Commission for Europe (ECE), Amsterdam, May 5-9, 1986, edited by T. Schneider, 189-221.
- 21) Chang, C.T., P. Monteiro, K. Nemati, and K. Shyu. "Behavior of marble under compression." *Journal of Materials in Civil Engineering*, Vol. 8, No. 3, August 1996, pp. 157-170.
- 22) Charola, A. Elena. "Laboratory Tests and Evaluation of Proposed Masonry Treatments." *APT Bulletin*, (no.1). 1996. 35-39.
- 23) Charola, A. Elena. "Water Repellent treatments for Building Stones: A Practical Overview." *APT Bulletin*, (no.2-3) 1995. 10-16.
- 24) Charola, A.E., and R.J. Koestler. "SEM Study of the Deterioration of Monumental Stones in Vienna." *Wiener Berichte uber Naturwissenschaft in der Kunst* 2-3 (1985-86). 176-186.
- 25) Charola, A.E., and R.J. Koestler. "Scanning Electron Microscopy in the Evaluation of Consolidation Treatments for Stone." *Scanning Electron Microscopy* (1986): 479-484.
- 26) Charola, A. Elena, and J. Delgado Rodeigues. "Discussions and conclusions of the roundtable on water-repellent treatments." *Science and Technology for Cultural Heritage*, 5 (1), 1996. 111-114.
- 27) Charola, A.E., A. Tucci, and R.J. Koestler. "On the Reversibility of Treatments with Acrylic/Silicone Resin Mixtures." *Journal of the American Institute of Conservators* 25 no. 2 (1986): 83-92.
- 28) Chute, Newton E. "Structural and mineralogical features of the Stockbridge marble and Berkshire schist near Adams, Massachusetts." *Economic Geology in Massachusetts*. Amherst: University of Massachusetts Graduate School, 169-179.

- 29) Clark, Elizabeth J., Paul G. Campbell and Geoffrey Frohnsdorff. "Waterproofing Materials for Masonry." Institute for Applied Technology, National Bureau of Standards: Washington, DC. 1975.
- 30) Clifton, James R. "Stone Consolidating Materials - A Status Report." NBS Technical Note 1118. Center for Building Technology: Washington DC, 1980. Conservation of Historic Stone Buildings and Monuments. Report of the Committee on Conservation of Historic Stone Buildings and Monuments. National Materials Advisory Board. National Academy Press: Washington, DC, 1982.
- 31) Cohen, Julie Mark, and Paulo J. M. Monteiro. "Durability and Integrity of Marble Cladding: A State-of-the-Art Review." *Journal of Performance of Constructed Facilities*, v. 5, no. 2, May 1991, 113-124.
- 32) Conti, Guilo. *Marble in the World*. Translated by Sandra Berresford, 2nd edition Carrara: Societa' Editrice Apuana, 1990. 7-56, 139-188.
- 33) Dana, Edward Salisbury. *A Text Book of Mineralogy with an Extended Treatise on Crystallography and Physical Mineralogy*. 41st edition, revised, New York: John Wiley & Sons, 1926.
- 34) De Casa, G. et al. "Study for Consolidation and Protection of Proconnesian Marble." In *Conservation of Stone and Other Materials. Volume 2: Prevention and Treatments*, 768-774. Edited by M.J. Thiel. London: E & FN Spon, 1993.
- 35) *Deterioration and Preservation of Stones*. Proceedings of the 311 International Congress. Venezia, 1079.
- 36) D'Ossat, Gulielmo 13e Angelis. *Guide to the Methodical Study of Monuments and Causes of Deterioration*. English text revised by June Taberoff and Cynthia Rockwell. Rome: ICCROM. 1982. 5-13.
- 37) Eastes, John W., and John W. Salisbury. "Spectral Properties of Sulfated Limestone and Marble: Implications for In Situ Assessment of Atmospheric Pollution Damage to Carbonate Roc Building Material." *Applied Spectroscopy* 40 no. 7. 954-959.
- 38) Fassina, V., et al. "Protective Treatment for the Reliefs of the 'Arconi di San Marco' in Venice: Laboratory Evaluation." *Durability of Building Materials* 5 (1987): 167-181.
- 39) Feddema, Johannes J. "Air Pollution Effects on Marble Weathering in Philadelphia, Pennsylvania," *Publications in Climatology*. Volume XXXIX, Number 1, 1086. Felix, G., ed. 5th International Congress on Deterioration and Conservation of Stone, Vol. A-2, Lausanne, 1985.
- 40) Franzini, Marco. "Stones in monuments: natural and anthropogenic deterioration in marble artifacts." *European Journal of Mineralogy*, Stuttgart, 1995, 7: 735-743.
- 41) Garzonio, C. A. et al. "Analyses of the physical parameters correlated to bending phenomena in marble slabs." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier, 1989, v. 1, pp. 89-98.
- 42) Gaud, K. Lai, et al. "Reactivity of Treated and Untreated Marble Specimens in an SO₂ Atmosphere." *Studies in Conservation* 18 (1973): 25-35.

- 43) Gaud, K. Lal, et al. "The Sulfation of Marble and the Treatment of Gypsum Crusts." *Studies in Conservation* 34 (1089): 201-20f.
- 44) Gauri, K. Lal, Niraj P. Kulshreshtha, Adinarayana R. Punuru, and Ahad N. Chowdhury. "Rate of decay of marble in laboratory and outdoor exposure." *Journal of Materials in Civil Engineering*, Vol. 1, No. 2, May 1989, 73-85.
- 45) Geological Survey of Pennsylvania. Harrisburg, PA: Pennsylvania Geological Society, 1891.
- 46) Giamello, M., G. Guasparri, R. Nevi and G. Sabatini. "Building Materials in Siena Architecture: Type, Distribution and State of Conservation." *Science and Technology for Cultural Heritage*. Giardini Editore a Stampatori: Pisa, 1092, 55-67.
- 47) Gilchrist, Agnes Addison. *William Strickland: Architect and Engineer*. Philadelphia: University of Pennsylvania Press, 1950.
- 48) Giorgio, Rodorico and Piero Baglioni. "New results in the application of innovative experimental techniques for investigation of stone's decay processes." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier, 1989, v. 1, 587-594.
- 49) Grimm, Wolf-Dieter. "Beobachtungen und Überlegungen zur Verformung von Marmorobjekten durch Gefügeanflöckerung." *Zeitschrift der Deutschen Geologischen Gesellschaft*, Stuttgart, 1999, v. 150, 195-235.
- 50) Grimmer, Ann E., ed. *Glossary of Historic Masonry Deterioration Problems and Preservation Treatments*. NPS Preservation Assistance Division: Washington, DC, 1984.
- 51) Gross, Christian J., Klaus Weber, Axel Vollbrecht, and Siegfried Siegesmund. "Cathodoluminescence and electron microprobe study of dolomite marbles from Namibia: evidence for hydrothermal alteration." *Zeitschrift der Deutschen Geologischen Gesellschaft*, Stuttgart, 1999, v. 150/2, 333-357.
- 52) Guidetti, V. and M. Uminski. "Ion exchange resins for historic marble desulfatation and restoration." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier, 1989, v. 2, 327-334.
- 53) Herz, Norman. "Petrofabrics and classic archaeology." *American Journal of Science*, New Haven, 1954, v. 253, 299-305.
- 54) Jain, Kamal K., Vimal K. Saxena, and Tej Singh. "Studies on the Effect of Biogenic Acids on Stone Materials." In *Biodeterioration of Cultural Property*, 20-25 February 1989, 240-248. Edited by O.P. Agrawal and Shashi Dhawan. ICCROM, 1989.
- 55) Julien, Alexis A. "The durability of building stones in New York City and vicinity," *Tenth Census of the United States*, v.10. Washington: Government Printing Office, 1884.
- 56) Kessler, David W. "Physical and chemical tests on the commercial marbles of the United States," *Technologic Papers of the Bureau of Standards*. Government Printing Office: Washington, 1919.
- 57) Kessler, David W. and R.E. Anderson. "Stone exposure test wall." *National Bureau of Standards Building Materials and Structures Report 125*. Department of Commerce, 1949.

- 58) Klein, Cornelis, and Cornelius S. Huribut, Jr. *Manual of Mineralogy*. 2111 edition. New York: John Riley and Sons, 1993.
- 59) Kocks, U.F. *Texture and Anisotropy: Preferred Orientations in Polycrystals and Their Effect on Material Properties*. Cambridge: Cambridge UP, 1998.
- 60) Koestler, R.J., A.E. Charola and G.E. Wheeler. "Scanning Electron Microscopy in Conservation: The Abydos Reliefs." *Proceedings of the Fifth International Seminar on Applications of Science in Examination of Works of Art*, Boston: 1983, 225-29.
- 61) Kulshreshtha, Niraj P., Adinarayana R. Punum, K. Lal Gauri, "Kinetics of reaction of SO₂ with marble." *Journal of Materials in Civil Engineering*, Vol. 1, No. 2, May 1989, 60-72.
- 62) Lewin, Seymour Z. and A. Elena Charola. "Stone decay due to foreign inclusions." *Preprints of the Contributions to the International Symposium and the Conservation of Stone: Part A, Deterioration*. Bologna, 1981.
- 63) Lindborg, Ulf et al. "Thermal stress and weathering of Carrara, Pentelic, and Ekeberg marble." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier, 1989, v. 1, pp. 109-118.
- 64) Lorenz, Heinz G. and Hermann Wolf Ibach. "Marmorknoservierung durch die IBACH volltrankung: qualidtskontrolle and optierung durch mikroskopische and petrophysikalische untersuchungen." *Zeitschrift der Deutschen Geologischen Gesellschaft*, Stuttgart, 1999, v. 150, 397-406.
- 65) MacKenzie, W.S. and A.E. Adams. *A Color Atlas of Rocks and Minerals in Thin Section*. New York: John Wiley and Sons, 1994.
- 66) Mairinger. F and M. Schreiner. "New Methods of Chemical Analysis - A Tool for the Conservator." *Science and Technology in the Service of Conservation*. Preprints of the Contributions to the Washington Congress, September 3-9, 1982. International Institute for Conservation of Historic Works: London. 5-13.
- 67) Malagodi, M et al. "Effects of combined application of biocides and protectives on marble." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier, 1989, v. 2, 225-234.
- 68) *Marble: Art Historical and Scientific Perspectives on Ancient Sculpture*. Symposium organized by the Departments of Antiquities and Antiquities Conservation, J. Paul Getty Museum: Santa Monica, 1990.
- 69) *Masonry: Repointing Masonry; Exterior Cleaning of Historic Masonry Buildings; Moisture Problems in Historic Masonry Buildings*. Division of Design and Construction Management, Landmarks Program, New York City. 1981.
- 70) Matero, Frank, et.al. *Historic Masonry Deterioration and Repair Techniques - An Annotated Bibliography*. NPS, Preservation Assistance Division: Washington DC, 1993.
- 71) Matero, Frank G. and Alberto Tagle. "Cleaning, iron stain removal and surface repair of architectural marble and crystalline limestone: the Metropolitan Club." *Journal of the American Institute for Conservation* 1995, v. 34, no. 1, Spring, 49-68.
- 72) McGee, Elaine S. "Influence of microclimate on the deterioration of historic marble buildings." *Association for Preservation Technology Bulletin*, 1991, v.23, n.4, pp. 3742.

- 73) McGee, Elaine. Acid Rain and Our Nations Capital -A Guide to Effects on Buildings and Monuments. U.S. Government Printing Office: Washington, LC, 1992.
- 74) McKee, Charles J. Introduction to Early American Masonry - Stone, Brick, Mortar and Plaster. National Trust for Historic Preservation: Washington, LC, 1973: 9-33, 61-71.
- 75) Merrill, George. Stones for Building and Decoration. New York: John Wiley & Sons. 1910.
- 76) Merrill, George E. "The collection of building and ornamental stones in the U.S. National Museum: a handbook and catalogue," in Annual Report of the Board of Regents of the Smithsonian Institution, showing the operations, expenditures, and conditions of the institution for the year ending June 30, 1886, Part II. Washington: Government Printing Office, 1889.
- 77) Miller, Benjamin LeRoy. Limestones of Pennsylvania. Harrisburg, PA: Pennsylvania Geological Survey, 1934.
- 78) Mills, Michael J. And Edmund P. Meade. Making Magic: Suspended Columns at Princeton's Whig and Clio Halls." APT Bulletin, Volume 3, 1997: 7-11.
- 79) Mitchell, David J. et al. "The influence of building orientation on climate weathering cycles in Staffordshire, U.K." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier, 1989, v. 1: 357-366.
- 80) Monk, C.B., Jr. "The rational use of masonry." Proc., Third North Am. Masonry Conf., Cost. Res. Ctr. Arlington: University of Texas, 1985.
- 81) Nesse, William D. Introduction to Optical Mineralogy. Second edition. New York: Oxford University Press, 1991.
- 82) Park, Sharon. "Moisture in Historic Buildings and Preservation Guidance." Moisture Control in Buildings. ASTM Manual Series: MNL 18: Philadelphia, 1994. pgs. 402-419.
- 83) Poschlod, Klaus. "Pore structure and properties of marbles." Proceedings of the 1st International Symposium on the Conservation of Monuments in the Mediterranean Basin. Bari, 1989, pp. 259-262.
- 84) Pray, Lloyd C., ed. Dolomitization and Limestone Diagenesis. Tulsa: Society of Economic Paleontologists and Mineralogists, Publication No. 13. 1965.
- 85) Price, C.A. Stone Conservation. Getty Conservation Institute: Santa Monica, 1996.
- 86) Reddy, Michael. "Acid rain and air pollution effects on carbonate-stone: dissolution/runoff experiments. Proceedings of the 1st International Symposium on the Conservation of Monuments in the Mediterranean Basin. Bari, 1989, pp. 359-363.
- 87) Reeder, Richard J., and Steven A. Markgraf. "High-temperature crystal chemistry of dolomite." American Mineralogist, 1986, v. 71, pp. 795-804
- 88) Rodrigues, J. Delgado, Fernando Henriques, F. Telmo Jeremias. Proceedings of the 7th International Congress on Deterioration and Conservation of Stone, Vols. 1-3. Lisbon, 1992.

- 89) Rohatsch, A. et al. "Physical properties of fine-grained marble before and after treatment." Proceedings of the 9th international congress on deterioration and conservation of stone. New York: Elsevier, 1989, v. 2: 453-458.
- 90) Rosenholtz, J.L., and D.T Smith. "Linear thermal expansion of calcite, var. Iceland spar, and Yule marble." American Mineralogist, v. 34: 846-854.
- 91) Ross, K.D. and R.N. Butlin. Durability Tests for Building Stone. Building Research Establishment Report. Garston, UK, 1989.
- 92) Rossi-Manaresi, Raffaella, ed. The Conservation of Stone II. Preprints of the Contributions to the International Symposium, Bologna, 1981.
- 93) Roth, Michael. "Comparison of Silicone Resins, Siliconates, Silanes and Siloxanes as Water Repellent Treatments for Masonry." Technical Bulletin 983-1, by ProSoCo, Inc.
- 94) Sabbioni, Christina et al. "Analytic methodologies for carbon compound identification: Leaning Tower and Baptistery of Pisa." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier, 1989, v. 1: 383-390.
- 95) Schaffer, R.J. The Weathering of Natural Building Stones. London. 1932: 43-65.
- 96) Selwitz, Charles. Epoxy Resins in Stone Conservation. Getty Conservation Institute: Santa Monica, 1992.
- 97) Schmid, J., M. Ambuhl, D. Decrouez. S. Muller, and K. Ramseyer. "A quantitative fabric analysis approach to the discrimination of white marbles." Archaeometry, 1999, v. 41: 239-252.
- 98) Searle, David E. et al. "The effects of coal and diesel particulates on the weathering loss of two major building stones in the United Kingdom-A comparative microcatchment study." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier. v. 1: 391-400.
- 99) Shaw, Edward. Operative Masonry: Or A Theoretical and Practical Treatise of Building. Boston: Marsh, Capen and Lyon, 1832: 11-33.
- 100) Sheremeti-Karabashi, Florife and Rolf Snethlage. "Determination of structural anisotropy of Carrara marble with ultrasonic measurements." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier, 1989, v. 1: 247-254.
- 101) Sherwood, Susan I., et.al. Distribution of Materials Potentially at Risk from Acidic Deposition. Report 21. National Acid Precipitation Assessment Program, NPS: Washington DC, 1990.
- 102) Sherwood, Susan I. and Donald A. Dolske. "Acidic deposition and marble monuments at Gettysburg National Military Park." Association for Preservation Technology Bulletin, 1995, v.23, n.4: 52-57.
- 103) Sherwood, Susan I., et.al. Processes of Deposition to Structures. Report 20. National Acid Precipitation Assessment Program. NPS: Washington, DC, 1990.

- 104) Siano, S. et al. "Integration of laser with conventional techniques in marble restoration." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier. v. 2: 569-576.
- 105) Siegesmund, S., A. Vollbrecht, K. Ullemeyer, T. Weiss, and R. Sobott. "Anwendung der geologischen gefügekunde zur charakterisierung natürlicher werksteine-fallbeispiel: Kauffunger marmor." Internationale Zeitschrift für Baunstandsetzen, Stuttgart, 1997, v. 3: 269-292.
- 106) Siegesmund, S. and R. Snethlage. "Control of marble weathering by thermal expansion and rock fabrics." Proceedings of the 9th International Congress on Deterioration and Conservation of Stone. New York: Elsevier, 1989, v. 1: 205-214.
- 107) Siegesmund, Siegfried, Thomas Weiss, Axel Vollbrecht, and Klaus Ullemeyer. "Marble as a natural building material: rock fabrics, physical and mechanical properties." Zeitschrift der Deutschen Geologischen Gesellschaft, Stuttgart, 1999, v. 150: 237-257.
- 108) Siegesmund, Siegfried, Klaus Ullemeyer, Thomas Weiss, Elmar K. Tschegg. "Physical weathering of marbles caused by anisotropic thermal expansion." International Journal of Earth Sciences, 2000, v. 89, pp. 170-182.
- 109) Siegesmund, Siegfried. "The significance of rock fabrics for the geological interpretation of geophysical anisotropies." Geotektonische Forschungen 85: 1-123. 1996.
- 110) Sixth International Congress on Deterioration and Conservation of Stone, Vols. 1-2. Nicholas Copernicus University Press: Torun, 1988.
- 111) Sleater, Gerald. "A Laboratory Test Program for Stone Preservatives." In Proceedings of the UNESCO-RILEM International Symposium on Deterioration and Protection of Stone Monuments 2 (no. 6.13): 1-19. Paris: Centre Experimental de Recherches et d'Etudes du Batiment et des Travaux Publics, 1978.
- 112) Sleater, Gerald A. A Review of the Subject of Natural Stone Preservation. Center for Building Technology: Washington DC, 1973.
- 113) Smith, Laird M. "Moisture problems in historic masonry walls: diagnosis and treatment." Washington, D.C.: U.S. Dept. of the Interior, 1980.
- 114) Snethlage, Rolf, Hans Ettl, and Ludwig Sattler. "Ultraschallmessungen an PMMA-getrankten Marmorskulpturen." Zeitschrift der Deutschen Geologischen Gesellschaft, Stuttgart, 1999, v. 150, pp 387-396.
- 115) Sterflinger, Katja, Wolfgang E. Krumbein, and Jürgen Rullkötter. "Patination of marble, sandstone and granite by microbial communities." Zeitschrift der Deutschen Geologischen Gesellschaft, Stuttgart, 1999, v. 150, pp. 299-311.
- 116) Stone, Ralph W. Building Stones of Pennsylvania. Harrisburg, PA: Pennsylvania Geological Survey, 1932.
- 117) Thomasen, S.E., and C.S. Ewart. "Durability of thin-set marble." Proceedings of the Third International Conference on Durability of Building Materials and Components, Philadelphia: ASTM, 1984.
- 118) Torraca, Giorgio. Porous Building Materials. Rome: ICCROM, 1988.

- 119) Tschegg, Elmar K., Clemens Widhalm, and Walter Eppensteiner. "Ursachen mangelnder Formbeständigkeit von Marmorplatten." *Zeitschrift der Deutschen Geologischen Gesellschaft*, Stuttgart, 1999, v. 150, pp. 283-297.
- 120) Vlahou, C., P. Kremezis, C. Pavlatos, P. Plainis and C. Floros. "Proposed Standards for the Design of the Rehabilitation of Monuments or Important Urban Nuclei." *Structural Conservation of Stone Masonry*. Rome: ICCROM, 1990. P.651-658.
- 121) Waite, John G. and Roger J. Cheng. "A case study of the cleaning and conservation of marble at the Schenectady, New York, City Hall." *Special Technical Publications 935*, American Society of Testing and Materials. ASTM: Philadelphia. 1987.
- 122) Webster, Robin G.M., ed. *Stone Cleaning and the Nature, Soiling and Decay Mechanisms of Stone*. Proceedings of the International Conference held in Edinburgh. Donhead: London, 1992.
- 123) Weiss, Norman R. "Development and assessment of a conversion treatment for calcareous stone." *Proceedings of the 9th International Congress on Deterioration and Conservation of Stone*. New York: Elsevier. v. 1, pp. 533-540.
- 124) Weiss, Thomas, Bernd Leiss, Heidrun Opperman, and Siegfried Siegesmund. "Microfabric of fresh and weathered marbles: implications and consequences for the reconstruction of the Marmorpalais, Potsdam." *Zeitschrift der Deutschen Geologischen Gesellschaft*, Stuttgart, 1999, v. 150, pp. 313-332.
- 125) Widhalm, Clemens, Elmar Tschegg, and Walter Eppensteiner. "Acoustic emission and anisotropic thermal expansion when heating marble." *Journal of Performance of Constructed Facilities*, Feb. 1997, pp. 35-40.
- 126) Widhalm, Clemens, Elmar Tschegg, and Walter Eppensteiner. "Anisotropic thermal expansion causes deformation of marble claddings." *Journal of Performance of Constructed Facilities*, Feb. 1996, pp. 5-10.
- 127) Wilson, Forrest. *Building Materials Evaluation Handbook*. New York: Van Nostrand, 1984. p.283-298.
- 128) Wilson, F. "The perils of using thin stone and safeguards against them." *AIA Journal*, v.78 (2), pp. 96-97.
- 129) Winkler, Erhard M. *Stone in Architecture*. 3rd edition. Springer-Verlag: Berlin, 1994.
- 130) Winkler, Erhard M. "Technical Note: Properties of Marble as Building Veneer," *International Journal of Rock and Mechanical Mineralogical Science & Geomechanical Abstracts*, v. 33 (2) pp. 215-218, 1996.
- 131) Winkler, Erhard M. "Weathering of crystalline marble," in *Proceedings of the International Symposium on the Engineering Geology of Ancient Works, Monuments, and Historical Sites: Preservation and Protection*. Athens, 19-23 September 1988, edited by Paul G. Marinos and George C. Koukis, 717-721. Rotterdam: A.A. Balkema, 1988.
- 132) Winkler, Erhard M. "Weathering of crystalline marble at the Field Museum of Natural History, Chicago." *Association for Preservation Technology Bulletin*, 1991, v.23, n.4, pp.43-47.

- 133) Winkler, Erhard M. "Weathering of Crystalline Marble: New Results." *Science, Technology, and European Cultural Heritage. Proceedings of the European Symposium, Bologna, 13-16 June 1989*, edited by N.S. Baer, C. Sabbioni, and A.I. Sors, 415-417. Oxford: Butterworth-Heinemann Ltd., 1991.
- 134) Yerrapragada, Srinivas S., Surendra R. Chirra, John H. Jaynes, S. Li, Jayanta K. Bandyopadhyay, K. L. Gauri. "Weathering rates of marble in laboratory and outdoor conditions." *Journal of Environmental Engineering*, Vol. 122, No. 9, September 1996, pp. 856-863.
- 135) Young, William J, ed. *Applications of Science in Examination of Works of Art. Proceedings of the Seminar Conducted at the Research Laboratory, Museum of Fine Arts, Boston, MA. 1970.*

10.2 Unpublished Sources

- 1) Batchelor, Penelope. "1974-1976 Construction Phase Masonry Construction Methods Used," Appendix VI of "Historic Structure Report Historical and Architectural Data First Bank of the United States." INHP Archives: Philadelphia, 1981.
- 2) Batchelor, Penelope. "Census of Treated Historic Buildings." William Brookover's File, INHP: Philadelphia, 1982.
- 3) Batchelor, Penelope. Notes. 12 December 1973. Historic Architect's Files, INHP: Philadelphia.
- 4) Batchelor, Penelope to Superintendent of INHP. Memorandum. 10 November 1975. Historic Architect's File, INHP: Philadelphia.
- 5) Brookover, William. Color Slide. September 1975. William Brookover's Files, INHP: Philadelphia.
- 6) Brookover, William. Commentary on memorandum from District Ranger to Safety Officer. 30 January 1992. William Brookover's Files, INHP: Philadelphia.
- 7) Brookover, William. Conversation with James Toner or Dawn Melbourne. 30 August 1995.
- 8) Brookover, William. Photograph. 1986. William Brookover's Files, INHP: Philadelphia.
- 9) Brookover, William to Ross Flanagan. Memorandum. 13 August 1986. William Brookover's Files, INHP: Philadelphia.
- 10) Colbourn, Robert J. "Historical Data," Chapter 2 of "Historic Structure Report of the Second Bank of the United States." INHP Archives Historic Building File: Philadelphia, 1962.
- 11) Condit, F.S. President of the Obelisk Waterproofing Company to Stewardson & Page, Estimate, 31 August 1922, AIA Archives and Library.
- 12) Crane, Architect Edward to Supervising Architect James A. Whitmore. 16 February 1923, AIA Archives and Library.

- 13) Denver Service Center. "Specifications Adaptive Restoration and Rehabilitation Second Bank of the United States." Historic Building File, INHP: Philadelphia, 1973.
- 14) Doyle, Stone Mason Frank. Conversation with James Toner or Dawn Melbourne. August 1995.
- 15) Dysert, Gary. "A Report on the Use of Fluoride Brick and Stone Cleaners." Historic Building File, INHP Archives: Philadelphia, 1963,
- 16) Elk, Sally and Linda Berger. "Pennsylvania Marble - The Stone of the New Republic: It's Rise, Characterization, Quarry Locations and Decay Mechanisms." Unpublished seminar paper at the University of Pennsylvania, 1997.
- 17) Gaud, K.L. "Conservation of the First Bank of the United States, Philadelphia: A Case History." INHP Archives: Philadelphia, 1974.
- 18) Glavan, John. "An Evaluation of Mechanical Pinning treatments for the Repair of Marble at the Second Bank of the United States." University of Pennsylvania Masters Thesis in Historic Preservation, 2004.
- 19) Heller, Harold. "An Approach to the Restoration and Preservation of the First Bank," Appendix V of "Historic Structure Report of the First Bank of the United States." INHP Archives: Philadelphia, 1981.
- 20) Heller, Harold. "Preservation of Historical Masonry Structures" Technical Proposal, NPS contract CX-4450-3-0008. INHP Archives: Philadelphia, 1974.
- 21) Kimmel, Jocelyn. "Characterization and Consolidation of Pennsylvania Blue Marble, with a Case Study of the Second Bank of the United States, Philadelphia, PA." University of Pennsylvania Masters Thesis in Historic Preservation, 1996.
- 22) Kornich, John. Report to Historic Architects. 7 October 1986. William Brookover's File, INHP: Philadelphia.
- 23) Lewin, S.Z. "Conservation of the Façades of Historic Buildings at Independence National Historic Park - Final Report." NIPS Contract 4000-1-0055. INHP Archives: Philadelphia, 1984.
- 24) Matero, Frank. "Ohio Statehouse Restoration, Masonry Surface Treatments, Section 04520." Contract Specifications, 1991.
- 25) McArthur, Superintendent of Public Buildings John to Supervising Architect for the Treasury Department A. B. Mullett, 7 January 1873, Historic Architect's File, INHP Archives: Philadelphia.
- 26) Morrison, Craig. Notes from meeting with Mike Callaghan Marble Shop. Historic Architect's Files, INHP: Philadelphia.
- 27) Munsch, Guy. "Reevaluating Success: A Conditions Assessment and Analysis of Previous Treatments of The First Bank of the United States." University of Pennsylvania Masters Thesis in Historic Preservation, 1998.
- 28) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, May 1942.

- 29) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 21 January 1964.
- 30) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 17 August 1964, negative # 8613, photograph by W.A. McCullough.
- 31) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, April 1971, negative # 10307A, photograph by W.A. McCullough.
- 32) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 2 May 1974, negative # 157.4315.32, photograph by Eisenman.
- 33) National Park Service, INHP Archives, Photograph Collection, Unaccessioned, Second Bank of the United States, 8 May 1986, photograph by William Brookover.
- 34) Naudé, Virginia. "Survey of Exterior Marble, Second Bank of the United States, Philadelphia, PA," 1994.
- 35) "Old Philadelphia Custom House." 2 Historic Building File, INHP Archives: Philadelphia, 1947.
- 36) Petrak, Joseph. "Historic Structure Report of the Second Bank of the United States." Historic Building File, INHP Archives: Philadelphia, 1964.
- 37) Petrak, Joseph to the Superintendent. Memorandum, 9 October 1969. Historic Architect's Files, INHP.
- 38) Preservation of the Lincoln and Jefferson Memorials: Stone Conservation Program. Architectural Conservation Laboratory, Graduate Program in Historic Preservation, University of Pennsylvania, Philadelphia, PA.
- 39) Report to Historic Architects. 28 April 1989. Historic Architect's File, INHP: Philadelphia.
- 40) Rier, Superintendent John to Acting Assistant Architect B. Bertly, 26 October 1865, Historic Architect's File, INHP Archives: Philadelphia.
- 41) Simon, Grant M. "Report on the Preservation of the Exterior Masonry of the Buildings forming a part of the Independence National Historic Park in Philadelphia with particular reference to the First Bank, the Second Bank and the Merchants' Exchange." NPS contract 14-10-0529-2410. INHP Archives: Philadelphia, 1961.
- 42) Strickland, William to Collector Judge Blythe, 9 December 1844, Historic Architect's File, INHP Archives: Philadelphia.
- 43) Vitetta Group, "Master Plan for the Restoration, Modernization and Rehabilitation of the Philadelphia City Hall." Masonry Conditions Survey and Analytical Testing Results. 1994.
- 44) Ware, Robert. "A Comparison of Fresh and Weathered Marble from the Tweed Courthouse." University of Pennsylvania Master's Thesis in Historic Preservation, 2001.

11.0 Appendix

11.1 Appendix A. Guidelines

11.1.1 Phase 1 AutoCAD Guidelines

Phase 1 of the project was completed in AutoCAD 14 software by Autodesk. Future versions of this software or compatible software should be able to open these drawing files.

The following information summarizes the key coordination guidelines for Phase 1 of the project.

CAD LAYERS

Every condition recorded as well as distinct architectural features (i.e. joints) has been placed in its own layer. This allows conditions (layers) to be turned off or on to view the drawings in more than one relational context.

DRAWING FILES

Each elevational drawing has been developed and saved as a drawing file in the folder marked "xref". The final drawings are composed of a single title block brought into paper space as an xref, with the elevation areas brought into model space. Multiple viewports have been used in paper space to compose the layout of the final drawings. Any raster images used in the drawings have been stored in a separate images folder.

LINE WEIGHTS

A single line weight was used for all of the conditions except for "major cracks", which has a double thickness. Modifications to the line weights were made using the creation of a plot file (pc2 file). This plot file can be loaded through the print dialog box prior to sending the drawing to the plotter.

PLOT FILES

Plot files were created for these drawings at a full size sheet (34" x 22") and half size sheet (17" x 11"). All drawings were plotted from a Hewett Packard DesignJet 750C Plus on Azon 27 lb. Premium Color Paper. Plot files must be configured to be compatible with the plotter to be used. The pen weights below will then need to be assigned and saved as a new plot file to be compatible with any plotter other than the model used for this drawing set.

AutoCAD PEN COLORS & LINE WEIGHTS

In general, set line widths to “0”. Plotted line widths and colors are determined by associating an AutoCAD color number (1 to 256) with a “pen” number of specific width in black and/or a color. The colors and weights used allow for the drawing conditions to be “readable” in both color and black and white. The following chart can be adapted for inkjet, laser, electrostatic or thermal plotting:

AutoCAD COLOR & PEN ASSIGNMENTS

Color/Pen No.	Color/Pen No.	Plot Size		Description/Example Use
		Pen Size Full Plot	Pen Size Half Plot	
100% no screen	50% screen			
1 (1) Red	Not used	0.009	0.005	Requires Intervention Conditions
75 (75) Med. Green	Not used	0.009	0.005	Requires Monitoring Conditions
145 (145) Med. Blue	Not used	0.009	0.005	Routine Maintenance-Observation Conditions
7 (7) White/Black	Not used	0.012	0.007	Outlines, text
8 (8) Grey	Not used	0.007	0.004	Stone Numbers
250 (250) Black	Not used	0.008	0.004	Thin black line
251 (251) Black	Not used	0.010	0.005	Medium black line
6 (6) Magenta	Not used	0.008	0.004	View Ports (Freeze for plotting)

For this project a full size plot is 34” wide x 22” high. A half size plot is 17” wide x 11” high. If an oversize plot is needed (125%) the size is 42.5” wide x 27.5” high.

11.1.2 Phase 2 Guidelines

A combination of Autodesk AutoCAD 2004, ESRI ArcMap 8.2, Adobe InDesign, and Adobe Acrobat software was used to complete the Phase 2 drawings. Final drawings are saved as portable document files (.pdf’s) and can be opened with Adobe Acrobat software. Drawings were plotted from Adobe Acrobat on both full size (36” x 24”) and half size (17” x 11”) sheets. All drawings were plotted from a Hewlett Packard DesignJet 1055CM. Sets of the plotted 1999, 2004, and updated 1999 drawings are in the collection of the archives of Independence National

Historical Park and at the Architectural Conservation Research Laboratory at the University of Pennsylvania.

ArcView COLORS & HATCH PATTERNS

ArcView software was used to display and represent the data because it offers a greater variety of colors and hatch patterns and allows for easier manipulation and fine tuning of the layers. The following table lists all of the conditions with the colors and hatches used to represent them in the final drawings:

SECOND BANK CONDITION SURVEY
COLORS AND HATCHES USED IN ARCMAP

CONDITION	COLOR	LINE/OUTLINE WIDTH	SYMBOL	PICTURE FILL	
Outlines	Gray 30%	.5	straight line		
Perspective (columns)	Gray 30%	.5	dashed 6:6		
SUBTRACTIVE CONDITIONS					
Open Joint	Mars Red	.5	Dike 2 Approx (Geology 24K)		*****
Deteriorated Mortar	Dark Umber	.5	Dike 2 Approx (Geology 24K)		*****
Major Crack	Mars Red	.5	Square Marker Size 4		*****
Moderate Crack	Leather Brown	.5	Square Marker Size 4		*****
Network Map Cracking	Olivenite Green	.4		haeshd20	
Friability/Flaking	Med. Coral Light	.4		ordered20	
Contour Scaling	Med. Coral Light	.4	0° lines, separation=3		
Differential Erosion	Med. Coral Light	.4	45° lines, separation=3		
Incipient Spalling	Peony Pink			Solid	
Dimensional Loss	Mars Red			Solid	
ADDITIVE CONDITIONS					
Repointing Repair	Larkspur Blue	.5	Dike 2 Approx (Geology 24K)		*****
Filled Crack Less Than 1	Permian 3	.5	Square Marker Size 4		*****
Filled Crack Greater Than 1	Larkspur Blue	.5	Square Marker Size 4		*****
Chemical Bird Repellent	Larkspur Blue	.4		ordered20	
Treatment Coating	Larkspur Blue	.4		620 Clay or Clay Shale	
Stone Redressing	Larkspur Blue	.4	-45° lines, separation=3		
Stone Dutchman	Big Sky Blue	.4		Solid	
Stone Unit Replacement	Cyan=5% Black=5%	.4		Solid	
Composite Repair	Sodalite Blue	.4		Solid	
Sealant	Ultra Blue	.4		Solid	

OTHERS					
Intrinsic Metallic Staining	Tertiary 2	.4		ordered40	
Extrinsic Metallic Staining	Tertiary 2	.4	Marker V size 5 (caves symbols) Separation: x=6, y=6		
NonIntrinsic Staining	Yucca Yellow	.4	0° lines separation =2		
Microflora	Fern Green	.4		smallwave2	
Encrustation	Cherrywood Brown	.4		ordered20	
Efflorescence	Jadeite	.4		ordered20	
Mineral Inclusion	Medium Yellow	.4		Solid	
Defective Mechanical Systems	Anemone Violet	.4		Solid	

11.2 Appendix B. Budgeting: Hours Allocated by Task

During both phases of the Conditions Assessment of the Second Bank, in addition to cumulative hours for the field school staff, the hours were broken down into specific work categories. These categories were used to assist in planning, staffing and expenses for future phases and to provide some baseline information to evaluate other assessment techniques or systems that may represent an improvement in savings of time, funding, or as a means to directing more of a focus towards the critical parts of the assessment process.

Over the entire field school period, hours were tracked for the following:

Phase 1

	<u>6 Interns (total hours)</u>	<u>Manager</u>
Archival Research	36	12
Field Survey	460.5	23
Digital Input	671.5	25
Photography/Imaging	10	18
Report Writing	13.5	56
Plotting	12	30
Coordination	193	69
Admin/Budget	0	18
Materials/Treatment Analysis	5	8
Total	1401.5 hrs.	259 hrs.

Comments relative to the above:

The areas for significant improvement are in the digitizing of the survey data and the coordination of the field work and digitizing.

Coordination as a category included a weekly meeting, reviewing drawings, adjusting surveys and the general operational types of tasks that occur on a daily basis.

The budgeted amount of time for management and coordination of the project (142 hours) was inadequate.

By using drawings for the baseline survey documents, photography hours were minimized.

These hours include the preparation work prior to the six week field school, and post- field school digitizing, plotting and report writing.

Phase 2

	<u>5 Interns (total hours)</u>	<u>Manager</u>
Field Survey	1000	
Digital Input	350	
Final Production	100	
Total	1450 hrs.	320 hrs.

Total Project 3430.5 person-hours

11.3 Appendix C: Masonry Conditions Glossary


CONDITION

Orientation of foliation planes


DEFINITION

Stones display a pattern of orientation based on their foliation planes. For edge-oriented stones, the position of these planes can be (a) horizontal, (b) vertical, or (c) diagonal to the ground. For face oriented stones, foliation planes are (d) parallel to the face of the stone.


GRAPHIC




(a) edge-oriented horizontal



(b) edge-oriented vertical



(c) edge-oriented diagonal



(d) face-oriented parallel


PHOTOGRAPHS




(a) edge-oriented horizontal



(b) edge-oriented vertical



(c) edge-oriented diagonal



(d) face-oriented parallel

CONDITION

Mineral Inclusions

DEFINITION

Stones may display large mineral inclusions as veins or phenocrysts. These inclusions are at least 1/2 inch in width and noticeably larger than prevailing foliation patterns. They are typically (a) raised in relief or (b) weathered out and are often distinctive in color and texture from the surrounding stone matrix.


GRAPHIC



PHOTOGRAPHS



(a) Raised in relief



(a) Raised in relief



(b) Weathered out



(b) Weathered out


CONDITION

Network cracking


DEFINITION

A patterned network of fine intersecting cracks occurring on the surface of the stone, often in association with mineral inclusion-rich areas.

PHOTOGRAPHS



GRAPHIC



CONDITION

Moderate cracking

DEFINITION

Cracks that are 1/16-1/8 inch (1.6-3.2 mm) wide, of varying orientation and depth. These can be either (a) structural or (b) those that occur along foliation planes.

PHOTOGRAPHS



(a) Structural crack



(b) Foliation crack

GRAPHIC



(a) Structural crack

CONDITION

Major cracking

DEFINITION

Cracks greater than 1/8 inch (3.2 mm) wide, of varying orientation and depth. Usually associated with (a) deformation / displacement and/or (b) incipient spalling.

PHOTOGRAPHS




(a) deformation or displacement



(b) incipient spall

GRAPHIC



(b) incipient spall

CONDITION

Friability / Flaking

DEFINITION

Surfaces with a) active disaggregation of individual grains and/or b) shallow flakes that dislodge under finger pressure.

GRAPHIC



PHOTOGRAPHS



a)



b)



b)

CONDITION

Differential erosion

DEFINITION

Surface weathering defined by (a) large areas of coarse texture, (b) localized loss greater than 1/4 inch in depth along foliation planes and in areas of mineral inclusions, or (c) reduction of surface details (e.g. weathered arrises or edges).

GRAPHIC



PHOTOGRAPHS



(a) Coarse texture



(b) Localized loss



(c) Reduction of surface details

CONDITION

Contour scaling / Exfoliation

DEFINITION

Distinctive localized or overall patterns of stepped irregular surface loss associated with foliation, where the surface loss is greater than 1/8 inch in depth.

GRAPHIC



PHOTOGRAPHS



CONDITION

Incipient spalling


DEFINITION

Surface planar discontinuities that have become partially separated from the parent stone. The detached area can be detected visually and audibly by sounding. The angle of separation will be approximately 0-60° from the surface plane of the surrounding stone and usually in association with foliation.

GRAPHIC



PHOTOGRAPHS




CONDITION

Dimensional loss

DEFINITION

Localized stone loss greater than 2 square inches in area and at least ½ inch in depth as measured in plane with the surrounding stone surface. This may or may not be in association with spalling.

PHOTOGRAPHS



GRAPHIC



CONDITION

Deformation / Displacement


DEFINITION

Movement and cracking or separation of one or more stones resulting in the shifting of stone surfaces more than 1/2 inch out of plane. Relative planar shifts recorded as (+) or (-).

PHOTOGRAPHS



GRAPHIC




CONDITION

Open joints

DEFINITION

Stone joints where the pointing mortar is lost and the joint open to the weather.

GRAPHIC



PHOTOGRAPHS




CONDITION

Deteriorated mortar joint

DEFINITION

Stone joints where the mortar is still present but eroded back 1/2 inch or more in depth, or noticeably cracked, or separated from the stone.

GRAPHIC



PHOTOGRAPHS



CONDITION

Efflorescence


DEFINITION

White crystalline, water-soluble deposits on the surface or within the pores of the stone indicating the presence of damaging salts.



PHOTOGRAPHS

GRAPHIC



CONDITION

Metallic staining

DEFINITION

Localized discoloration resulting from the weathering of either (a) intrinsic (mineralogical) or (b) extrinsic (copper or iron accessories) sources, usually black/brown (iron) or blue/green (copper) in color.

PHOTOGRAPHS




(a) intrinsic staining



(b) extrinsic staining

GRAPHIC



Intrinsic Metallic Staining



Extrinsic Metallic Staining


CONDITION

Encrustation

DEFINITION

Formation of gray to black smooth deposits or framboidal crusts in protected areas that are noticeably more concentrated than the prevailing soiling patterns.

GRAPHIC



PHOTOGRAPHS


CONDITION

Microflora

DEFINITION

Localized zones of biological growth including algae, fungi, and lichens visible as a black, greenish or brown discoloration. Many of these areas are on the lower sections of the building, under windowsills, and along the cornice area at the tree line.

GRAPHIC



PHOTOGRAPHS



CONDITION


Chemical bird repellent treatments

PHOTOGRAPHS

DEFINITION

Residue of chemical gels and coatings used on horizontal surfaces to deter birds from landing and nesting on the building.

GRAPHIC



PENNSYLVANIA BLUE PROJECT, INDEPENDENCE NATIONAL HISTORICAL PARK
MASONRY CONDITIONS GLOSSARY

CONDITION

Sealant repair

DEFINITION

Presence of elastomeric sealants used as a masonry repair or pointing material.

PHOTOGRAPHS



GRAPHIC





CONDITION

Repointing

DEFINITION

All non-original mortars used for repointing joints, usually gray or white in color and often in association with joint recutting.

PHOTOGRAPHS



GRAPHIC



CONDITION

Stone Dutchman


DEFINITION

Stone infill repair set into the surrounding masonry
(a) with or (b) without mortar.


GRAPHIC



PHOTOGRAPHS



(a) dutchman with mortar



(b) dutchman without mortar



(a) dutchman with mortar



(a) dutchman with mortar

CONDITION

Filled cracks

DEFINITION

Repairs to cracks executed at any time (a) less than 1/4 inch in width.

Repairs to cracks executed at any time (b) greater than 1/4 inch in width.




(a) Less than 1/4 inch




(b) Greater than 1/4 inch

GRAPHIC

(a)



(b)



CONDITION

Tooling marks

DEFINITION

Stones that are relatively protected still display their original surface tooling marks. The tooling marks are a relative indicator of the degree of surface weathering of the stone. The condition was recorded only where the tooling is evident on at least 50% of the stone's surface.

PHOTOGRAPHS




Replacement stone tooling



Original stone tooling

GRAPHIC



CONDITION

Composite Repairs

DEFINITION

A mortar or resin based system, used as a surface repair greater than 3/4 inch in width for spalls and overall losses, including those along joints, but not for cracks.

GRAPHIC



PHOTOGRAPHS




CONDITION

Stone Replacement

DEFINITION

Physical and/or archival evidence that complete stones or sections of the building, terraces, or perimeter walls have been replaced. Include date if known.

GRAPHIC



PHOTOGRAPHS



1976



1938

CONDITION

Previous treatment coatings


DEFINITION

The past application of a coating on the stone surface, generally off-white or pale yellow in color.

PHOTOGRAPHS



GRAPHIC



MASONRY CONDITIONS GLOSSARY

CONDITION

Stone redressing

DEFINITION

Tooling marks that indicate the selective redressing of stone to address advanced surface deterioration.

GRAPHIC



PHOTOGRAPHS



PENNSYLVANIA BLUE PROJECT, INDEPENDENCE NATIONAL HISTORICAL PARK
MASONRY CONDITIONS GLOSSARY

CONDITION

Defective mechanical features

DEFINITION

Building systems and/or anchoring hardware that is contributing to a stone deterioration condition.



PHOTOGRAPHS

GRAPHIC



PENNSYLVANIA BLUE PROJECT, INDEPENDENCE NATIONAL HISTORICAL PARK
MASONRY CONDITIONS GLOSSARY

CONDITION

Condition unique

DEFINITION

Any condition or physical alteration to the original surface of the building which does not fit within the existing set of categories. Numbering is sequential but does not reflect a specific order to the conditions.

GRAPHIC



PHOTOGRAPHS

PENNSYLVANIA BLUE PROJECT, INDEPENDENCE NATIONAL HISTORICAL PARK
MASONRY CONDITIONS GLOSSARY

CONDITION

Historic conditions

DEFINITION

Historic photographs that provide a time-based comparison of stone loss, weathering, and soiling patterns.

PHOTOGRAPHS




1961



2004

GRAPHIC



11.4 Appendix D: Overview of 1999 Database of Conditions

Stone Numbering:

Each stone of the north and west elevations were assigned unique stone numbers based on the elevation, architectural element, stone course, and stone number. Courses are numbered from the ground up. Stones are numbered from left to right. All of the stone numbers are shown on the four Stone Numbering Drawings: North Elevation Wall, Pediment, Column and West Elevation.

For example:

North Elevation + Wall + 4th Course from the ground + 5th Stone from the left = NW4.5

North Elevation + Column 6 + 3rd Drum from the ground + South face = NC6.3S

Abbreviations used for stone numbering:

North Wall = NW

North Pediment = NP

North Columns = NC

North Interior Portico (refers to underside and backside of portico) = NP

West Wall = WW

West Foundation = WF

West Chimneys = WCh

Index

- ACL.....i, 2
 analysis.... 2, 4, 6, 14, 18, 22, 23, 24, 52, 53, 56, 58, 65
 Architect... 3, 7, 9, 10, 12, 13, 14, 15, 16, 17, 62, 68, 69, 70
 Architectural Conservation Laboratory . See : ACL.
 ArcView.....4, 5, 6, 58, 73
 Assessmenti, 22, 26, 61, 65, 69, 75
 Athenaeum7
 AutoCAD.....4, 5, 6, 71, 72
 Batchelor, Penny 12, 13, 14, 16, 68
 Brookover, William...i, 12, 16, 17, 18, 53, 60, 68, 69, 70
 calcite..... 14, 19, 20, 21, 52, 54, 55, 56, 65
 carbonate..... 19, 20, 54, 55, 56, 59, 64
 Celanese Coatings Incorporated.....16
 cleaning 9, 10, 13, 14, 18, 20, 67
 Clearstone18, 53
 columns . 2, 4, 5, 7, 9, 10, 11, 13, 14, 15, 17, 18, 21, 58
 concrete15
 Crane, Edward.....10, 68
 Custom House.....10, 11, 70
 database4, 56
 decay 16, 19, 20, 21, 22, 24, 58, 62, 63
 detergents.....11
 deterioration... 1, 3, 4, 5, 6, 7, 10, 16, 18, 19, 20, 21, 24, 25, 56, 58, 59, 61, 63, 65
 diagnosis.....23, 66
 diurnal21
 dolomite19, 20, 62, 64
 Dysert, Gary.....12, 69
 efflorescence20
 Epi-rez 510 16
 epoxy 8, 12, 16, 17, 18
 FINOLA Abrasive Scouring Powder15
 fluoride12, 13, 14, 18
 foliation19, 21
 Free Library7
 General Electric Co14
 GIS.....2, 6, 58
 graffiti17
 gypsum 20, 21, 52, 55, 56
 HABS4
 Heller, Harold.....14, 69
 Henderson Quarry7
 Historic American Buildings Survey..... See :HABS
 HVAC.....14
 Hydrozo8, 13, 18, 53
 Independence National Historical Parki, 2, 6, 7, 9, 73
 INHP See: Independence National Historical Park
 Kornich, John 17, 69
 Larson Products..... 15
 Latrobe, Benjamin..... 1
 lime 9, 58
 maintenance 9, 16, 17, 22, 24
 Masonry .. i, 9, 12, 14, 16, 59, 60, 61, 62, 63, 64, 65, 67, 68, 69, 70, 77
 Masury Columbia Company 15
 McArthur, John..... 10, 69
 Merchant's Exchange 1, 24, 52, 58
 methyl ethyl ketone..... 16
 Montgomery County 1, 7
 mortar..... 2, 9, 12, 15, 18, 24, 53, 58
 Mullett, A. B..... 10, 69
 National Park Service . i, 2, 5, 11, 12, 13, 16, 17, 19, 60, 69, 70
 National Portrait Gallery..... 14
 Naudé, Virginia 2, 17, 18
 Obelisk 10, 68
 Old City Hall 12
 paraffin 10, 18
 Pennsylvania Blue .. 1, 2, 3, 7, 20, 21, 54, 69
 Petrak, Joe..... 8, 12, 13, 70
 pH 14
 pigeon control 16
 plastic deformation..... 19
 poultice.....15
 prison See . See
 repairs . 2, 3, 7, 11, 14, 15, 16, 17, 18, 24, 58
 salts..... 18, 20
 scaffolding..... 4, 5, 13
 Scanning electron micrographs See:SEM
 Second Bank... i, 2, 3, 4, 7, 9, 11, 12, 13, 14, 16, 17, 18, 19, 21, 23, 25, 52, 53, 54, 58, 68, 69, 70, 75
 SEM 14, 52, 60
 silicate 14, 18
 sodium bicarbonate 12
 spalling..... 2, 10, 12, 13, 15, 16, 20, 21
 stabilization 2
 steam 11
 Strickland, William..... 1, 9, 10, 13, 62, 70
 structural 22, 24, 65
 temperature..... 20, 24, 64
 thermal 19, 21, 24, 65, 66, 67, 72
 treatment.... 1, 3, 4, 8, 10, 13, 16, 18, 21, 22, 52, 56, 58, 65, 66, 67
 University of Pennsylvania i, 2, 4, 5, 6, 7, 53, 62, 69, 70, 73
 water repellents..... 11, 58

water-proofing.....52
Weld-crete15
Winkler, Erhard M. 10, 14, 18, 67, 68

Wyandotte Detergent Powdered
Abrasive Cleaner..... 15
X-Ray Diffraction..... 53